Flight Procedures Cover Page	Task Action: FLIGHT CHECK	Task Type : IAP	Estimated Chart Date: 10/31/2024	APWS Task ID: 8E49C3C31675408B890600B7B207870A	APWS Project ID: CD24F7A5A0954CE7A0A6F17098D5BBB1		
Procedure: Enroute: VOR-A AMDT 5 NO		Enroute: NO	Specialist: Campbell, Colin		Agreement Number:		
Airport ID: KIPL			Airport City: IMPERIAL		State: CA		
Facility ID:	Facility Type:	Flight Inspection Remain New FC Slot	rk Type:				
Procedure Comments:							
SUMMARY OF CHANGES: GPS SPLIT OUT INTO NEW PROCEDURE. PROCEDURE ADJUSTED TO BE CIRCLING ALIGNED. MISSED APPROACH REDESIGNED TO MITIGATE CIH REQUIREMENT.							
ACTIVE AIRPORT DATA USED							
ACTIVE IPL VTAC DATA USED							
CONTACT: ALLAN WILL, AJV-A423, (405) 954-6103							
		011 00 /4 5 /00					
4/10/24: THIS IS AN UPDATED COPY OF	THE FORM DEVELOPED	UN 08/15/23.					
FORM 8260-5: 1. PROFILE LINE 8: UPDATED MSA FROM "IPL VORTAC 130-315 6700, 315-130 2300" TO "IPL VORTAC 130-315 6800, 315-130 2400".							
7/15/24: THIS IS AN UPDATED COPY OF THE FORM DEVELOPED ON 08/15/23.							
FORM 8260-2: 1. REMOVED IMPERIAL VORTAC -2 FROM 8260-2 FILE AND MOVED TO 8260-2_NON NFDC FILE.							
9/13/24: THIS IS AN UPDATED COPY OF THE FORM DEVELOPED ON 08/17/23.							
FORM 8260-2: FIX ARGUS: 1. REMOVED KIPL RNAV (GPS)-B FROM 2. REMOVED PAT 1 WITH ASSOCIATED C 3. HOLDING TYPE OF ACTION CHANGED FIX MAJGY: 1. REMOVED KIPL RNAV (GPS)-B FROM 2. REMOVED "WP" FORM FIX TYPE.	CONTROLLING OBSTRUC FROM "ESTABLISH" TO		REMARK.		ONALITL 10 CHECKEP		

				FI	PC BASIC	FOR	Μ						
PROCEDURE:				AIRPC	AIRPORT NAME: AI			AIRPO	RT ID:	SPECIAL CONTROL NO:			
VOR-A AMDT 5			IMPEF	IMPERIAL COUNTY KII			KIPL	CIPL 5		SP-05-204-24			
FAC ID: IPL	FAC ID: IPL CITY: IMPERIAL				ST: CA		ORIG CHART DATE: 09/05/2024						
DFL TYPE:	THIRD PART	i: EST. TI	EST. TIME ON SITE: REIMB. NUMBER: PTS TASK ID:					ID:	I				
PROC/A	ROC/A I YES 0.4 8E49C3C31675408E					675408B8	890600B7B207870A						
	PREFLIGHT NOTES												
REVIEWER:									DATE:				
COMMENTS:									CHECK (ONE:			
									🗌 FLT (CK REQ	NFCR	🗌 REJ	ECT
												YES	NO
									CPV COM	APLETE?		X	
PROCEDURE RESULTS													
INSPECTION DAT	TE: CF	EW #:	N #:		INSTRUMENT PROCEDURE STATUS:			ARINO	INC CODING:				
06/27/2024	V	1327	N83	X SAT SAT W/CHANGES UNSAT SAT/GOLD UN					NSAT				
FLIGHT INSPECT	OR SIGNATU	RE:		PRINTE	PRINTED NAME: NOTAM INITIATED?						ED?		
jeffrey eckman @ 06/27/2024 20:34			ECKMA	ECKMAN, JEFFREY ALAN					YES	XI	NO		
FLIGHT INSPECT Procedure is SAT as		S:											
IN-FLIGHT OBSTACLE REPORT													
OBSTRUCTION II	D #: COORD	INATES O	R LOCATION:	GNSS ALT	TITUDE (MSL):	BARC	METRIC A	ALTITUD	DE (MSL):	HEIGHT	ABOVE GRO	UND LE	EVEL:

1. FLIGHT PROCEDURE IDENTIFICATION:

IMPERIAL, CALIFORNIA IMPERIAL COUNTY (KIPL) VOR-A

2. WAIVER REQUIRED AND APPLICABLE STANDARD:

Turn from the intermediate segment to the final segment is 56.93 degrees, which exceeds the maximum allowed turn of 30 degrees. Applicable standard is FAA Order 8260.3E, paragraph 2-5-3(a).

3. REASON FOR WAIVER (JUSTIFICATION FOR NONSTANDARD TREATMENT):

A turn of 30 degrees or less at the NAVAID would take aircraft into Mexico airspace. After discussion with responsible ATC controlling agency, communication lines between Los Angeles Center Sector 9 and MXL have frequent outages and are at times unusable. Additionally, for proper procedure alignment, sector 9 would require a non-block down to acceptable altitude. This would require aircraft utilizing this procedure to enter Mexico airspace. Los Angeles Center Sector 9 does not display Minimum IFR Altitude (MIAs) beyond the US/Mexico border. Additionally, an update to the LOA between MXL and Los Angeles Center Sector 9 would be required. Sector 9 also advised that they are unsure as to what effect this would have to MMML Mexicali Airport.

4. EQUIVALENT LEVEL OF SAFETY PROVIDED:

This procedure is a replacement for an existing VOR or GPS procedure that has existed at this location for many years. Containing the procedure in US airspace greatly reduces complexity for both the pilot and controller/ATC facilities. The greater than standard turn at the NAVAID is required to keep the procedure within US Airspace.

5. ALTERNATIVE ACTIONS DEEMED NOT FEASIBLE:

1. Restricting the turn to 30 degrees or less would cause the procedure to enter Mexico Airspace and may disrupt ATC operations into MMML airport.

2. Approach procedures are unable to be constructed from other directions of arrival due to large areas of Restricted Airspace. Procedure build in any other direction would bring aircraft in restricted airspace to the north and northeast (R-2512 and R-2510 A&B. To the west would encroach El Centro NAF.

6. COORDINATION WITH USER ORGANIZATIONS (SPECIFY):

AFS SOCAL TRACON ZLA CENTER

7. SUBMITTED BY:

DATE	OFFICE IDENTIFICATION	TITLE
	AJV-A423	MANAGER

SIGNATURE

Digitally signed by ALLAN WILL Mar 13, 2024

8. AFS ACTIONS:

□ APPROVED □ DISAPPROVED □ NOT REQUIRED

COMMENTS:

DATE ROUTING SYMBOL SIGNATURE

1. FLIGHT PROCEDURE IDENTIFICATION:

IMPERIAL, CALIFORNIA IMPERIAL COUNTY (KIPL) VOR-A

2. WAIVER REQUIRED AND APPLICABLE STANDARD:

Turn from the Hold-In-Lieu and Missed Approach Holding Pattern to the final segment is 56.93 degrees which exceeds the maximum allowable turn of 30 degrees. Applicable standard is FAA Order 8260.3E, paragraph 16-9-2.

3. REASON FOR WAIVER (JUSTIFICATION FOR NONSTANDARD TREATMENT):

A turn of 30 degrees or less at the NAVAID would take aircraft into Mexico airspace. After discussion with responsible ATC controlling agency, communication lines between Los Angeles Center Sector 9 and MXL have frequent outages and are at times unusable. Additionally, for proper procedure alignment, sector 9 would require a non-block down to acceptable altitude. This would require aircraft utilizing this procedure to enter Mexico airspace. Los Angeles Center Sector 9 does not display Minimum IFR Altitude (MIAs) beyond the US/Mexico border. Additionally, an update to the LOA between MXL and Los Angeles Center Sector 9 would be required. Sector 9 also advised that they are unsure as to what effect this would have to MMML Mexicali Airport.

4. EQUIVALENT LEVEL OF SAFETY PROVIDED:

This procedure is a replacement for an existing VOR or GPS procedure that has existed at this location for many years. Containing the procedure in US airspace greatly reduces complexity for both the pilot and controller/ATC facilities. The greater than standard turn at the NAVAID is required to keep the procedure within US Airspace.

5. ALTERNATIVE ACTIONS DEEMED NOT FEASIBLE:

1. Restricting the turn to 30 degrees or less would cause the procedure to enter Mexico Airspace and may disrupt ATC operations into MMML airport.

2. Approach procedures are unable to be constructed from other directions of arrival due to large areas of Restricted Airspace. Procedure build in any other direction would bring aircraft in restricted airspace to the north and northeast (R-2512 and R-2510 A&B. To the west would encroach El Centro NAF.

6. COORDINATION WITH USER ORGANIZATIONS (SPECIFY):

AFS SOCAL TRACON ZLA CENTER

7. SUBMITTED BY:

DATE	OFFICE IDENTIFICATION	TITLE	
	AJV-A423	MGR	

SIGNATURE Digitally signed by ALLAN WILL


Sep 16, 2024

8. AFS ACTIONS:

□ APPROVED □ DISAPPROVED □ NOT REQUIRED


COMMENTS:

DATE ROUTING SYMBOL SIGNATURE



AUTOMATED AL-790 VOR-A

SW-3 03/09/24 COMPILER: JUN REVIEWER: DBL CHKR: EFF: FIG



SW-3, 13 JUL 2023 to 10 AUG 2023

SW-3, 13 JUL 2023 to 10 AUG 2023

