



DC-9

3855 Lakewood Boulevard
Long Beach, California 90801

REFERENCE:
BULLETIN 24-69

SERVICE BULLETIN SUMMARY

NOTE: This summary is for information only and is not FAA approved for modification of aircraft.

SUBJECT: ELECTRICAL POWER - Electrical Load Distribution - Replace Lavatory Flush Pump Motor Circuit Breakers.

breaker incorporating a unique current-time characteristic, will provide the maximum overheat protection without causing circuit breaker trips.

NOTE

The applicable group for affected aircraft is to be determined by the operator as follows:

Group I

Applicable to aircraft equipped with one lavatory.

Group II

Applicable to aircraft equipped with two lavatories.

Group III

Applicable to aircraft equipped with three lavatories.

ANALYSIS: Seven operators have reported overheating of the lavatory flush pump motor. The overheating may occur when the motor is exposed to either single-phase power or power with a locked rotor for an extended period of time. If not corrected, unscheduled maintenance of the lavatory flush pump motor may be required.

MODIFICATION DESCRIPTION: Replaces the 5-amp lavatory system flush pump motor circuit breakers with 1-amp circuit breakers on the ground service bus circuit breaker panel, on the left console or electrical power center, as applicable. Accomplishment of this modification, which installs a circuit


EFFECTIVITY: DC-9 Series 10, 20, 30, 40, 50, C-9, MD-81, and MD-82 aircraft. (See Service Bulletin 24-69 for detailed effectivity.)

COMPLIANCE: Recommended. To be accomplished at operator's convenience.

MANPOWER:

	Group		
	I	II	III
Total Man-Hours	1.5	2.0	2.2
Total Elapsed Hours	1.5	2.0	2.2

MATERIAL INFORMATION: DAC parts required to accomplish this modification are to be purchased from DAC as end item spares. Remaining parts are to be procured from operator's stock or supplier.



REPLACE LAVATORY FLUSH PUMP
MOTOR CIRCUIT BREAKERS

April 16/84

Reference Bulletin 24-69

DC-9

SERVICE BULLETIN

ELECTRICAL POWER - Electrical Load Distribution - Replace Lavatory Flush Pump Motor Circuit Breakers.

NOTE

The applicable group for affected aircraft is to be determined by the operator as follows:

Group I

Applicable to aircraft equipped with one lavatory.

Group II

Applicable to aircraft equipped with two lavatories.

Group III

Applicable to aircraft equipped with three lavatories.

1. Planning Information:A. Effectivity:(1) Aircraft Affected:

DC-9, Series 10, 20, 30, 40, 50, C-9, MD-81, and MD-82

(a) Operator and Aircraft Number:

<u>Operator</u>	<u>Factory Serial No.</u>	<u>Operator</u>	<u>Factory Serial No.</u>
AA	49145	AC (cont)	47024
	49155		47069
	49158 and 49159		47071
	49161 thru 49163		47195
	49167 and 49168		47198 and 47199
	49171 thru 49181		47265 and 47266
AC	45845		47289 and 47290
	47019		47292 thru 47294
	47021 and 47022		47340 thru 47342
			47348 thru 47350

MCDONNELL DOUGLAS CORPORATION (MDC) PROPRIETARY RIGHTS ARE INCLUDED IN THE INFORMATION DISCLOSED HEREIN AND RECIPIENT BY ACCEPTING THIS DOCUMENT AGREES THAT THE INFORMATION IS PROPRIETARY TO MDC. MDC AUTHORIZES RECIPIENT TO REPRODUCE SUCH INFORMATION IN OTHER DOCUMENTS CREATED FOR INTERNAL USE IF THESE DOCUMENTS ARE PROTECTED SIMILARLY BY A PROPRIETARY LEGEND.

<u>Operator</u>	<u>Factory Serial No.</u>	<u>Operator</u>	<u>Factory Serial No.</u>
AC (cont)	47353 and 47354 47422 47485 47546 47554 47557 47560 47592 47598 47611	AM (cont)	47594 47602 47607 47609 47650 48067 thru 48069 48083 48125 thru 48130 48150 and 48151 49149
AL	45868 47026 47050 thru 47054 47057 and 47058 47066 47099 47130 47146 47188 and 47189 47207 thru 47210 47212 47216 47310 47332 47334 thru 47336 47351 and 47352 47371 thru 47375 47420 and 47421 47429 47505 thru 47508 47564 47574 47576 47583 47588 47590 47593 48114 thru 48120 48131 48138 thru 48147 48154 thru 48159	AO	47080 47091 and 47092 47556 47637 47640 47642 thru 47644 47675 47678 47702 47704 47706 and 47707 48103 thru 48106
		AU	48024 and 48025 48050
		AY	45711 45725 45729 47044 and 47045 47604 thru 47606 47613 and 47614 47694 thru 47696 47736 thru 47738 47771 thru 47773 48134 thru 48136 49150 thru 49152
AM	45785 47006 47059 47085 47106 47122 and 47123 47125 thru 47127 47356 47394	AZ	47038 and 47039 47046 and 47047 47101 47128 and 47129 47222 and 47223 47225 47231 47233 thru 47236 47238 47283 47311 47339 49192 thru 49194

<u>Operator</u>	<u>Factory Serial No.</u>		<u>Operator</u>	<u>Factory Serial No.</u>	
BD	45712	and 45713	CO (cont)	47524	
	45719			47535	
	45738	and 45739		47539	
	47048			47765	
	47430			47788	
	47468			47797	thru 47799
BM			DL	48111	thru 48113
	47224				
	47226			47176	and 47177
	47228			47257	thru 47262
	47232			47273	thru 47278
	47431	thru 47438		47284	and 47285
	47474			47317	thru 47323
	47477			47358	and 47359
	47502			47377	thru 47379
	47518			47443	thru 47445
	47533		EA		
	47544			45733	and 45734
BQ	47575			45833	thru 45840
	47641			45863	thru 45867
				45869	
	47229	and 47230		45871	thru 45876
	47237			47036	
	47519			47074	
	47553			47098	
BW	47591			47119	thru 47121
	47653			47140	thru 47143
				47157	
	47742	and 47743		47161	
	47752			47165	thru 47167
	47796			47181	
BX	48122			47184	
				47186	and 47187
	47458			47214	and 47215
CA				47217	
	49140	and 49141		47268	thru 47272
				47327	thru 47331
CO				47399	
	45714	thru 45716		47401	thru 47403
	45726	and 45727		47665	
	45735	and 45736		47676	and 47677
	45742	and 45743		47679	
	45786			47682	and 47683
	45788			47685	and 47686
	45791			47688	and 47689
	45844			47692	and 47693
	45847			47728	
	47043			47731	thru 47733
	47062			47745	and 47746
	47110	thru 47112		47749	
	47218	and 47219		47751	
	47281			47753	
	47521				

<u>Operator</u>	<u>Factory Serial No.</u>	<u>Operator</u>	<u>Factory Serial No.</u>
EZ	47220 and 47221 47355	IB (cont)	47461 47496 47504 47522
FL	49102 49114 49116 thru 49118		47542 and 47543 47545 47565
GA	47385 and 47386 47481 47561 47569 47601 47635 and 47636 47701 47722 47730 47740 and 47741 47744 47789 thru 47795	IG IW II JD	47713 thru 47715 45696 45841 47408 47608 47612 47615 and 47616 47619 and 47620 47759 thru 47762 47767 and 47768 47780 and 47781 48029 thru 48033 48070 thru 48072
GB	45717 and 45718 45728 47002 47008 47040 47072 47147 47203 47380 and 47381 47426 and 47427	JK JU	45695 45795 45842 47425 47460 47469 and 47470 47472 and 47473 47532 47562 and 47563 47567 and 47568 47571 47582
GH	47755		
HA	47763 and 47764 48044 and 48045 48051 48058		
IB	47037 47076 47079 47084 47088 thru 47090 47093 47312 thru 47314 47364 and 47365 47368 47428 47446 and 47447 47452 thru 47456	KL KQ	45720 47102 47131 thru 47133 47168 thru 47170 47190 thru 47194 47201 47279 47462 47514 48132 and 48133 47478

<u>Operator</u>	<u>Factory Serial No.</u>	<u>Operator</u>	<u>Factory Serial No.</u>
LM	47648 47666 49123 and 49124	OC	48027 and 48028 48062 and 48063 48066 49112 and 49113
LV	47703 47705 47712 47719 thru 47721 47727 47770 47782	OD	45698 and 45699 45730 47010 47015 47060 47152
MC	47363 47659 and 47660 48056 and 48057 49120 thru 49122 49125	OQ	45843
ML	45737 45741 45776 45778 thru 45781 45783 and 45784 47005 47202 47527 47547 thru 47549 48026 48049	OS	47484 47555 47559 47651 and 47652 47726 47735 47756 48015 thru 48021 48059
NI	47148 47175 47291 47465 47639 48073 and 48074	OZ	45772 and 45773 45798 and 45799 47001 47027 thru 47030 47033 47035 47082 47095 and 47096 47107 thru 47109 47134 thru 47137 47172 thru 47174 47248 thru 47251 47324 47343 thru 47345 47357 47409 47411 and 47412 47491 47589 47603 47617 and 47618 47669 47734 48123 and 48124
NY	45789 45792 and 45793 47067 47094 47113 47315 and 47316 47423 and 47424 47487 47490 47520 47531 47638 49126 and 49127		

<u>Operator</u>	<u>Factory Serial No.</u>	<u>Operator</u>	<u>Factory Serial No.</u>
PS	45846	RC (cont.)	47346 and 47347
	47020		47362
	47023		47369 and 47370
	47068		47376
	48034 thru 48043		47382
	48052 and 48053		47389 thru 47391
	48092 thru 48099		47404 thru 47406
	49119		47415 thru 47417
	49138 and 49139		47439 and 47440
	49142 and 49143		47450
RC			47459
	45701		47517
	45703 thru 45705		47566
	45707 thru 45709		47572 and 47573
	45723		47647
	45744 thru 45749		47664
	45770		47708 thru 47710
	45787		47716 thru 47718
	45825		47724
	45827 thru 45832		47729
	47016 thru 47018		47739
	47031		47757 and 47758
	47041 and 47042		47769
	47049		47774 thru 47776
	47063 and 47064		47785 thru 47787
	47073		48054 and 48055
	47078		48086
	47083		48088 thru 48091
	47086		48100 thru 48102
	47103		48107 thru 48110
	47138 and 47139		48121
	47144 and 47145		48148 and 48149
	47149 and 47150		
	47153	SI	48079 and 48080
	47155 and 47156		49110 and 49111
	47158		
	47160	SK	47114 thru 47117
	47162 thru 47164		47178 thru 47180
	47171		47286 thru 47288
	47182 and 47183		47301 thru 47303
	47185		47305 thru 47308
	47204 thru 47206		47360 and 47361
	47240		47395 and 47396
	47244		47413 and 47414
	47246 and 47247		47464
	47252 thru 47256		47492 thru 47494
	47263 and 47264		47497 thru 47499
	47280		47509 thru 47513
	47337 and 47338		47596 and 47597

<u>Operator</u>	<u>Factory Serial No.</u>	<u>Operator</u>	<u>Factory Serial No.</u>
SK (cont)	47599 47610 47623 thru 47634 47646 47725 47747 and 47748 47750 47754 47766 47777 thru 47779	XZD	45826 47011
		YA	45732
		YBB	47479 47711 49101 49277
SR	45790 47282 47383 and 47384 47480 47523 47654 thru 47658 47661 thru 47663 47783 and 47784 48002 thru 48014 49100	YJP	47239 47392 47530 47570 47697 48046 48048 48087
		YLL	47672 and 47673 47680
TK	45774 47397 47442 47451 47488 and 47489 47534 47674 47723	YMP	48022 49144
		ZAF	47241 and 47242 47295 47297 thru 47300 47366 and 47367 47448 and 47449 47467 47471 47475 47495 47536 thru 47538 47540 and 47541 47668 47670 and 47671
TN	47007 47009 47326 47418 and 47419 47528 47550 thru 47552		
TW	49153 and 49154 49156 and 49157 49160 49165 and 49166 49169 and 49170 49182 thru 49187	ZBM	47087 47154
		ZCA	47061
VA	49103 and 49104	ZCP	47151
VE	45710 47104 and 47105	ZDF	45721 and 45722
		ZGM	45782

<u>Operator</u>	<u>Factory Serial No.</u>	<u>Operator</u>	<u>Factory Serial No.</u>
ZGU	45740	ZNX	45706
ZIG	47595 47600	ZN3	47012 47014 47055
ZKA	47309	ZRS	45797
ZKD	45775	ZSE	47013
ZKG	47690 and 47691	ZVB	47000
ZNV	47003 and 47004 47065 47325 47410 47476 47577 and 47578 47580 and 47581 47584 thru 47587 47681 47684 47687 47698 thru 47700 48137 48165 and 48166	ZWH	45731 47466 47486 47516 47525 47529
		ZY0	45702
		2C	47070

(b) Other Aircraft:

Factory Serial No.

47501
47526
48000

NOTE: Aircraft listed under Other Aircraft are affected by this Service Bulletin but were not assigned to any specific operator at time of Service Bulletin issue.

This modification will be incorporated prior to delivery on all applicable DC-9, Series MD-80 aircraft, manufacturer's fuselage number 1135 and subsequent.

(2) Spares Affected:

None.

B. Reason:

Seven operators have reported overheating of the lavatory flush pump motor. The overheating may occur when the motor is exposed to either single-phase power or power with a locked rotor for an extended period of time. If not corrected, unscheduled maintenance of the lavatory flush pump motor may be required. Replacing the 5-amp circuit breakers in the flush pump circuit with a 1-amp circuit breaker incorporating a unique current-time characteristic will provide the maximum overheat protection without causing circuit breaker trips.

C. Description:

All Groups

This modification replaces the 5-amp lavatory system flush pump motor circuit breakers with 1-amp circuit breakers on the ground service bus circuit breaker panel, on the left console or electrical power center, as applicable.

D. Compliance:

Recommended. To be accomplished at operator's convenience.

E. Approval:

The resultant modification described in paragraph 1.C has been shown to comply with the applicable Federal Aviation Regulations and is FAA approved for the affected aircraft listed in paragraph 1.A.

F. Manpower:

This modification may be accomplished in the following approximate man-hours or elapsed hours per aircraft:

<u>Work Phases</u>	<u>Man-Hours</u>		
	Group		
	<u>I</u>	<u>II</u>	<u>III</u>
Gain Access	0.2	0.2	0.2
Modify (Aircraft)	1.0	1.5	1.7
Close Up	<u>0.3</u>	<u>0.3</u>	<u>0.3</u>
Total Man-Hours	1.5	2.0	2.2
Total Elapsed Hours	1.5	2.0	2.2

NOTE: Man-hour estimates are calculated based on the assumption that the aircraft/unit has been placed in a maintenance status. The man-hour/elapsed time estimates do not include:

1. Preparation for the modification: Examples; defueling, purging, placing work stands, opening standard access doors, obtaining tools, and jacking when not essential to the modification.
2. Nonproductive elapsed time: Examples; sealant or adhesive cure time, cleaning, paint drying time, lunch and/or rest periods, and quality assurance inspections.
3. Administrative functions: Examples; planning, engineering liaison, parts requisition, shift change coordination, and report writing.

Operators should take the above into consideration when scheduling this modification.

G. Material - Cost and Availability:

(1) Aircraft:

Parts required to accomplish this modification are listed in paragraph 3.A and are to be procured as indicated. Parts with unit net prices are proprietary parts and must be purchased as end item spares from the Douglas Aircraft Company under the spare parts article of the purchase agreement. Unit net prices are subject to change by current pricing policies. Douglas Aircraft Company proprietary parts will be available in approximately 150 days after receipt of purchase order. Availability of supplier parts is to be negotiated between operator and supplier.

The purchase order must specify this Service Bulletin number and only parts listed herein. Direct purchase order to:

Douglas Aircraft Company
P.O. Box 1771
Long Beach, California 90801
Attn: Parts Sales - Commercial 7-21
(DC-9 Service Bulletin 24-69)

(2) Spares:

Not applicable.

H. Tooling - Price and Availability:

None.

I. Weight and Balance:

None.

J. References:

- (1) Douglas letter C1-75-41/TS/RWW (AOL 9-481), dated July 15, 1970, ATA File Code 9-38-30.
- (2) Douglas letter C1-750-226/TS/DA (AOL 9-1486), dated November 18, 1983, ATA File Code 9-38-30-0.
- (3) Douglas letter C1-750-254/TS/DA (AOL 9-1490), dated December 2, 1983, ATA File Code 9-24-0/9-38-30.
- (4) Douglas letter C1-750-254/TS/DA (AOL 9-1490A), dated January 27, 1984, ATA File Code 9-24-0/9-38-30.
- (5) Douglas letter C1-750-254/TS/DA (AOL 9-1490B), dated April 6, 1984, ATA File Code 9-24-0/9-38-30.
- (6) Data used in preparation of this Service Bulletin:

<u>Data Identification</u>	<u>Change</u>	<u>Type of Data</u>
7930620	HU, Memo 52	Drawing
*38-31-00		Wiring Diagram

*Page number will vary with operators.

K. Publications Affected:

The modification outlined in this Service Bulletin affects the following DAC DC-9 aircraft publications:

<u>Publication</u>	<u>Chapter and/or Section</u>
Illustrated Parts Catalog	24-50
Wiring Diagram Equipment List	
Wiring Diagram Manual	38-31

**2. Accomplishment Instructions:**

WARNING: TO AVOID INJURY TO PERSONNEL OR DAMAGE TO EQUIPMENT, MAKE CERTAIN ADEQUATE PRECAUTIONS ARE TAKEN WHILE PERFORMING ANY WORK IF ELECTRICAL POWER IS APPLIED TO THE AIRCRAFT.

CAUTION: ELECTRICALLY GROUND THE AIRCRAFT.

All Groups

A. Replace lavatory flush system pump motor circuit breakers as follows:

Left Console - Figure 1
Electrical Power Center - Figure 2

B. Close applicable circuit breakers and energize aircraft buses.

C. Push toilet flush button in lavatory and check for proper operation of lavatory flush system.

D. Change existing wiring diagram to reflect this modification.

GROUP I

- ① REPLACE 7274-55-5 CIRCUIT BREAKERS (ITEMS 81-373, 81-374, AND 81-375) WITH S00475-1 CIRCUIT BREAKERS.
- ② INSTALL THREE S7918246-1 REPAIR NAMEPLATES.

GROUP II

- ③ REPLACE 7274-55-5 CIRCUIT BREAKERS (ITEMS 81-373, 81-523, 81-374, 81-524, 81-375, AND 81-525) WITH S00475-1 CIRCUIT BREAKERS.


OR

REPLACE 7274-55-5 CIRCUIT BREAKERS (ITEMS 81-373, 81-370, 81-374, 81-371, 81-375, AND 81-372) WITH S00475-1 CIRCUIT BREAKERS.


- ④ INSTALL SIX S7918246-1 REPAIR NAMEPLATES.

GROUP III


- ⑤ REPLACE 7274-55-5 CIRCUIT BREAKERS (ITEMS 81-373, 81-370, 81-523, 81-374, 81-371, 81-524, 81-375, 81-372, AND 81-525) WITH S00475-1 CIRCUIT BREAKERS.
- ⑥ INSTALL NINE S7918246-1 REPAIR NAMEPLATES.



LAVATORY FLUSH PUMP MOTOR CIRCUIT BREAKER - REPLACEMENT



LAVATORY FLUSH PUMP MOTOR CIRCUIT BREAKER - REPLACEMENT



LAVATORY FLUSH PUMP MOTOR CIRCUIT BREAKER - REPLACEMENT

GROUP I


- ① REPLACE 7274-55-5 CIRCUIT BREAKERS (ITEMS 81-373, 81-374, AND 81-375) WITH S00475-1 CIRCUIT BREAKERS.
- ② INSTALL THREE S7918246-1 REPAIR NAMEPLATES.

GROUP II


- ③ REPLACE 7274-55-5 CIRCUIT BREAKERS (ITEMS 81-373, 81-370, 81-374, 81-371, 81-375, AND 81-372) WITH S00475-1 CIRCUIT BREAKERS.
- ④ INSTALL SIX S7918246-1 REPAIR NAMEPLATES.

GROUP III


- ⑤ REPLACE 7274-55-5 CIRCUIT BREAKERS (ITEMS 81-373, 81-370, 81-523, 81-374, 81-371, 81-524, 81-375, 81-372, AND 81-525) WITH S00475-1 CIRCUIT BREAKERS.
- ⑥ INSTALL NINE S7918246-1 REPAIR NAMEPLATES.




LAVATORY FLUSH PUMP MOTOR CIRCUIT BREAKER - REPLACEMENT



S7918246-1
REPAIR
NAMEPLATE
(6 PLACES) 4




LAVATORY FLUSH PUMP MOTOR CIRCUIT BREAKER - REPLACEMENT



**VIEW C
GROUP III**

S7918246-1
 REPAIR
 NAMEPLATES
 (9 PLACES)



LAVATORY FLUSH PUMP MOTOR CIRCUIT BREAKER - REPLACEMENT

3. Material Information:

A. The basis for the following material data is per aircraft.

(1) Parts to be purchased as end item spares.

<u>Part No.</u>	<u>Qty Per Group</u>			<u>Unit</u>	<u>Key Word</u>
	<u>I</u>	<u>II</u>	<u>III</u>	<u>Net Price</u>	
S7918246-1	5	6	9	\$17.10	Repair Nameplate

(2) Parts to be procured from operator's stock or supplier.

NOTE: FSCM indicates Federal Supply Code for Manufacturers.

<u>New Part No.</u>	<u>Qty Per Group</u>			<u>Key Word</u>	<u>Old Part No.</u>	<u>Instructions-Disposition</u>	
	<u>I</u>	<u>II</u>	<u>III</u>			<u>1/</u>	<u>2/</u>
S00475-1	3	6	9	Circuit Breaker	7274-55-5	<u>1/</u>	<u>2/</u>

1/ May be purchased from: Mechanical Products Incorporated
 Subsidiary of Amstar Technical Products Incorporated
 1824 River Street
 Jackson, Michigan 49204
 FSCM 76374

2/ Return old parts to stock if serviceable.

B. The basis for the following material data is per spares.

None.

LL
JEM