

Ordered For: J. A. Plumer

6.18

117

NACA 4326

AD No. 204447
ASTIA FILE COPY

NATIONAL ADVISORY COMMITTEE FOR AERONAUTICS

TECHNICAL NOTE 4326

AD-204447

FC
BAC

LIGHTNING HAZARDS TO AIRCRAFT FUEL TANKS

D. Robb, E. L. Hill, M. M. Newman, and J. R. Stahmann

Lightning and Transients Research Institute

FILE COPY
Return to
ASTIA
ARLINGTON HALL STATION
ARLINGTON 12, VIRGINIA
After 1958



Washington
September 1958

ASTIA
RECEIVED
OCT 23 1958
110 BK D

NATIONAL ADVISORY COMMITTEE FOR AERONAUTICS

TECHNICAL NOTE 4326

LIGHTNING HAZARDS TO AIRCRAFT FUEL TANKS

By J. D. Robb, E. L. Hill, M. M. Newman, and J. R. Stahmann

SUMMARY

The hazards of lightning strokes to aircraft fuel tanks have been investigated in artificial-lightning-generation facilities specifically constructed to duplicate closely the natural lightning discharges to aircraft determined through flight research programs and analysis of lightning-damaged aircraft over a period of many years. Explosion studies were made in an environmental explosion chamber using small fuel tanks under various simulated flight conditions.

The results showed that there is a primary hazard whenever there is direct puncture of the fuel-tank wall, whereas the ignition of fuel by hot spots on tank walls due to lightning strikes is unlikely. Punctures of fuel-tank walls by artificial-lightning discharges produced explosions of the fuel in the mixture range from excessively lean to rich mixtures. None of the aluminum alloys, 0.081 inch thick or over, were punctured by the laboratory discharges representative of natural-lightning discharges to aircraft; however, reliance on this wall thickness for complete protection would not be justified, because occasional strokes are known to be of greater magnitude and because statistics reveal variations in the damage pattern.

Data gathered by the Lightning and Transients Research Institute on lightning strokes to aircraft show that 90 percent of the strokes recorded have occurred in the temperature range of -10° to $+10^{\circ}$ C, where many of the jet fuels are flammable but where aviation gasoline is overrich. Also, 10 percent of the strokes recorded have been to the wings, which are the principal fuel-storage areas for modern aircraft. Thus, there is a hazard, particularly for jet fuels. Certain protective measures are indicated by the studies to date, such as the use of lightning diverter rods, thickening of the wing skin in areas near the most probable stroke paths, and the use of fuel-tank liners in critical areas.

INTRODUCTION

Aircraft flying in thunderstorm regions occasionally are struck by lightning, and the striking of a fuel tank may result in a fire or

explosion. A research program has been undertaken to evaluate this hazard by studying the basic mechanisms of fuel-tank ignition from lightning strokes in various environmental and flight conditions. The phases for which there is limited operating experience are especially emphasized; for example, the operational hazards arising from the use of jet fuels and of wingtip fuel tanks.

The characteristics of natural-lightning discharges to aircraft have been studied by the Lightning and Transients Research Institute (LTRI) through flight research programs, lightning-damage questionnaires, and the analysis of many damaged aircraft parts submitted for inspection by airlines and by the military services over a period of years. The data obtained indicate that a substantial number of strokes to aircraft involve electrical charge transfers as large as 200 coulombs but have relatively low current magnitudes and rates of rise of current. This suggests, as might have been expected, that many strokes to aircraft are of a cloud-to-cloud nature, but it does not preclude the possibility that a stroke to ground may be intercepted by an aircraft. Modern airliners usually fly over or through the upper regions of thunderstorms rather than under them where strokes to ground occur, except, of course, during the landing or takeoff periods.

Owing to the long path lengths of natural-lightning discharges, which may extend for many miles, the resistance of any short length of the path has little effect on the magnitude of the current, so that the discharge can be considered to originate from a constant-current generator. Therefore, the energy developed in an object depends mainly on the resistance (since the energy release is equal to I^2Rt , where I is the current, R the resistance, and t the time of discharge). Thus, considerably greater energies are released in resistive materials than in metals. For example, strokes to radomes produce damage over areas several feet in diameter, whereas strokes to metal aircraft skin seldom produce holes larger than an inch in diameter.

Aircraft parts that have been damaged by lightning show two general types of pitting. Strokes occurring toward the front parts of aircraft sections are swept to the rear by the motion of the plane; and, as the aircraft passes the relatively stationary ionized channel, small pit marks or holes are burned along the surface or edge. The energy is released over a relatively large area, so that it produces only a small amount of pitting at any one location. Strokes occurring directly to the front, and particularly those to the rear, of a section tend to hang on at a single point for a large fraction of the stroke duration and thus produce larger holes and more severe pitting.

When the lightning strokes are swept to the rear by the relative motion of the aircraft with respect to the stroke channel, the metal aircraft skin is frequently not punctured and the question naturally arises

whether a stroke that does not puncture a fuel-tank wall will cause ignition by heating of the wall. This was considered to be an important question concerning the degree of hazard, and a theoretical and experimental study of fuel-tank wall temperatures due to lightning currents was undertaken at the beginning of the investigation.

Other factors to be considered include the evaluation of the types and magnitudes of discharges required to puncture various fuel-tank walls, the conditions under which a subsequent explosion or fire can occur, and the effects of environmental conditions, fuel types, and fuel-tank location on explosion probability.

This investigation was carried out at the Lightning and Transients Research Institute under the sponsorship and with the financial assistance of the National Advisory Committee for Aeronautics.

APPARATUS AND PROCEDURE

The Lightning and Transients Research Institute (LTRI) has developed artificial-lightning-generation facilities that are particularly suitable for reproducing lightning effects on aircraft as determined by flight research programs made in cooperation with civilian airlines and the military forces. The photograph and cross section of the laboratory (fig. 1) show the location of the high-voltage facilities and the large door for bringing voltage outside the building to test objects such as the aircraft in the foreground.

LTRI facilities for lightning studies include a 5-million-volt impulse generator capable of producing a standard AIEE 1.5 \times 40-microsecond voltage wave (1.5 microsec to crest, 40 microsec to half voltage) and a high-current generator producing a 10 \times 20-microsecond standard AIEE current wave of over 100,000 amperes peak. Mixing the high-voltage and high-current generators makes it possible to reproduce some of the effects found in the lightning-damaged aircraft components studied. However, a comparison of these effects and the data from the flight research program shows that most lightning strokes to aircraft involve much larger charge transfers than are produced by the high-voltage and high-current waves heretofore adopted as lightning test standards in the power industry.

For producing the high charge components of the natural-lightning strokes, two additional generator facilities are used. One of these units consists of a 3000-microfarad bank of 10-kilovolt capacitors which, with appropriate wave-shaping inductance and resistance, produces a 2,000-ampere current of 20-coulomb charge transfer. The second unit consists of a source of 200 amperes d.c. that can be drawn at a source voltage of either 400 or 13,000 volts, depending on the length of the arc it is required to sustain. This unit reproduces the low-current, long-duration components of lightning discharges that have currents of the order of a few hundred amperes.

A schematic circuit diagram of all the generators with their composite lightning-discharge current waveform is shown in figure 2; and the effects of the various stroke components of the three current generators, which are the most important for metal fuel-tank damage studies, are tabulated in table I. The heating effects are given in terms of a multiplying factor for a given resistance. It is interesting to note that both the high-current and the long-duration low-current generators produce much less heating effect than the generator with intermediate current and charge transfer. The three units together produce the major characteristics of lightning strokes: large mechanical forces from the high initial current, a large amount of short-duration heating and blast effects from the intermediate currents, and erosion and pitting effects from the large coulomb transfers of the long-duration low current. The high-voltage generator can be used in conjunction with the current generators, but since it does not contribute significantly to the damage, it is more often used separately to determine the most likely points on aircraft sections or models that the lightning discharges will strike.

For model fuel-tank explosion studies a cylindrical steel tank, 9 feet in diameter and 15 feet high, was constructed to contain explosions and to permit evacuation for altitude testing. A blower supplied by the NACA was connected to the tank for studying windstream effects, and a wind-tunnel section was constructed through the tank interior as illustrated in figures 3 and 4. A 6- by 6-inch cross section at the tunnel throat produced the desired wind velocity of 300 mph. The tank was constructed with large, thick windows for photographic use and special high-voltage bushings for introducing high-voltage discharge at reduced air pressures corresponding to high altitudes. A short plenum chamber, packed with 2-inch furnace pipe to straighten out the airflow, was constructed to join the exponential section that reduced to the Plexiglas throat. A Pitot-static tube and airspeed indicator were used to calibrate the tunnel; a constant velocity of about 300 mph was indicated over most of the throat area. One section of the throat was left open to receive the fuel tanks.

Measurement equipment included an NACA recording mixture analyzer, a potentiometer for thermocouple temperature measurement, an oscilloscope for measuring fuel-tank pressures as determined with a piezoelectric gage, and other miscellaneous equipment, all located outside the tank for protection from the explosions. Much of this equipment was electrically grounded to the tank; and, since the impulse ground-conduction currents raised the tank itself to substantial voltage, an isolation transformer was used to feed all equipment requiring a 115-volt source. A carbon dioxide fire extinguisher was attached to the outside of the tank with a nozzle connected through the wall, aimed at the fuel-tank sample. Thus, any fires following fuel-tank explosions were easily extinguished from the camera operator's position. The scale fuel-tank explosion tests gave

as much difficulty as any high-voltage experiments made in this laboratory because of the large amount of equipment involved and the many test-run failures before the first successful tests were made.

The operations included energizing the 13.8-kilovolt substation to obtain sufficient power for the wind-tunnel blower, charging the three artificial-lightning generators used to produce the composite discharge, setting the automatic timing devices for limiting the long-duration low current, resetting the many overload circuit breakers, measuring fuel-air ratio and temperature, and adjusting cameras and miscellaneous equipment such as lights, and so forth. Although successful test runs required careful setups for each test and good coordination from the operators, it was felt that further construction to obtain completely automatic operation was not justified for the number of tests contemplated.

Gasoline explosions of fuel tanks, even partially filled, constitute a severe fire hazard; and, since explosions of full-size tanks were felt to be a necessary part of the studies, provisions were made for reducing the hazard to a minimum by confining possible explosions. A large pit with concrete-block walls was constructed to confine the explosions to a space next to the building beside the door where voltages and currents could be brought out with relatively short leads, as illustrated in figure 5. The 40-foot-square door allowed maximum voltages to be brought out to the pit test area. The 150-horsepower blower installed in the pit behind suitable asbestos or block barricades provided the necessary flow of air over the tank surface.

A special foam fire-extinguisher system for protecting the area was installed, consisting of a 1,000-gallon tank located at the top of the laboratory building; a centrifugal pump, adding 100 pounds pressure to the 20-pound tank head; foam supply and foam proportioner; two large foam nozzles at each end of the pit, having capacities of 110 gallons per minute each; and the required 2- to 3-inch connecting pipes. For extinguishing localized fires and protecting the laboratory building, a 100-foot auxiliary hose that can be equipped with either a foam playpipe or a water-fog nozzle was provided. The capacity was sufficient to cover the floor of the pit with about 0.7 foot of foam. This system was considered adequate to extinguish possible fires, but the local community fire department could also be called immediately for additional protection in the event that the limited water supply proved to be inadequate.

The control and observation area in the building is indicated in figure 5. All high-voltage controls as well as fire-extinguishing controls and voltage and current waveshape monitoring equipment are located in this area. Two cameras were used in recording the tank explosions, a 16-millimeter motion-picture camera located near the pit and a Fastax camera located on the building roof. The Fastax camera recorded any phenomena that occurred too rapidly for accurate recording by the standard movie camera.

RESULTS AND DISCUSSION

Measurement of Fuel-Tank Wall Temperature

A lightning stroke hitting the outer surface of a fuel-tank wall or of a structural member containing fuel vapors may puncture the wall with a good probability of producing explosion and fire; if the wall thickness is too large to puncture, the stroke increases the temperature of the inner surface of the wall. The stroke will usually cause a small crater of molten metal to form in the outside of the wall, which produces pitting of the surface. Part of the molten metal is displaced by the explosive force of the sudden heating, but part solidifies to add to the heat flowing into the wall. The temperature of the inner surface attains its maximum value directly under the point of stroke contact and decreases rapidly at other points along a radial line from this point on the inner surface. The purpose of this section is to determine, both theoretically and experimentally, possible temperature-time curves for points on the inner surface of a fuel-tank wall when lightning strikes the outer surface. The hazard due to these "hot spots" is evaluated in a later section. Symbols used are defined in appendix A.

When a discharge hits a plate and does not puncture it, the heat is conducted to the inner surface, raising the temperature of that surface, and is also conducted radially from the point of stroke contact and dissipated in the remainder of the plate. In the theoretical study of the heat flow in a plate (appendix B), a block on the surface of the plate of depth β and of square cross section is assumed to be instantaneously heated to a uniform temperature which, for a lightning discharge, is taken to be about $1,200^{\circ}$ F, the melting temperature of aluminum. The heat flow from the block into the plate is then calculated from the heat-conduction equation to obtain the temperature at any point in the plate as a function of the time. The calculations are simplified by computing only the temperatures on the inner surface and by letting the breadth of the plate approach infinity, since the size of the plate does not materially affect the heat flow to the inner surface so long as the thickness is small compared with the other dimensions of the plate. Graphical examples giving the numerical results obtained by using these solutions for a hot spot directly under the discharge and for a point near this spot are also presented in appendix B.

Temperatures were measured experimentally in the large cylindrical environmental chamber shown in figure 6 so that the effects of temperature, airstream, and altitude could also be studied. The simulated discharge was directed to the test plate through the high-voltage bushing in the top of the tank. A block diagram of the thermocouple system is shown in figure 7. The thermocouple wires had to be carefully shielded in the vicinity of the tank. Two shields, insulated from each other and

4935

connected only at one point, were used between the thermocouple box and the wall of the chamber. The outer shield carried the heavy discharge currents to the wall, while the inner shield provided additional shielding from electric fields and from any possible unsymmetrical current distribution in the outer shield. The thermocouple voltages were transmitted to the amplifiers and recording equipment in a multiconductor shielded cable.

The instrumentation for these measurements was set up to measure peak temperatures from about 500° F, roughly the spontaneous-ignition temperature of JP-4 fuel, to about 1,200° F, the melting point of aluminum. The oscillograph was considered the best method of recording the rise and decay of the temperature-time curves and the peak temperatures. Iron-constantan thermocouples with size 36 wire were selected for this purpose because of their adequate sensitivity, availability, and sufficiently low thermal inertia to permit accurate measurement of temperature variations at a point. A box about 7 inches square and 2 inches deep shielded the thermocouples from the large simulated-lightning discharge current. Test plates of various representative wall thicknesses were used as top covers for the box, and simulated discharges were directed to the center of the plate. The thermocouples were placed at a point directly beneath the center of the plate and on a radial line from this point. The thermocouple voltages were amplified by d-c amplifiers having a 9-megohm input impedance. The amplifier outputs drove Brush recorders with an over-all sensitivity of about 35° F per millimeter of pen deflection. The maximum chart speed of the recorder was 71 inches per minute, or about 34 milliseconds per millimeter of chart movement. A selector switch was provided for viewing or recording waveforms on a single-channel cathode-ray oscillograph.

The theoretical results of appendix B indicate relatively low temperature peaks at points other than the point directly under the discharge, and the explosion test results of the following section indicate that wall punctures caused explosions but that there were no explosions definitely attributed to inner-wall heating. For this reason most measurements were taken at the point directly under the discharge. The theoretical temperature-time curve for the inner surface of a 1/8-inch aluminum plate with a block, uniformly and instantaneously heated to the melting point of aluminum, was calculated from the equations and curves developed in appendix B. The block was assumed to be in the outside surface of the plate, 0.5 centimeter square and 0.159 centimeter (1/16 in.) deep.

Fifteen high-current discharges were used in the experimental phase of the wall-temperature study. A cross section through the center of an actual crater obtained by discharging a laboratory lightning stroke to a 1/8-inch aluminum test plate is shown in figure 8. This crater is about

0.045 inch deep because of molten metals that have been spattered from the point of stroke contact. However, some of the metal below the crater floor was also heated to the melting point, perhaps to a depth of about 1/16 inch or one-half the wall thickness.

The theoretical temperature-time curve for a 1/8-inch aluminum plate is shown in figure 9(a), and the corresponding experimental curve is shown in figure 9(b). The two curves agree reasonably well. The rise times of the two curves are about the same. The slightly delayed, higher and longer peak of the experimental curve was probably due to the latent heat of fusion of the molten aluminum not displaced, which would tend to store heat at a constant temperature, and also to the fact that the discharge was not applied instantaneously but supplied heat to the plate continuously for about 20 milliseconds. The slightly higher tail on the experimental curve at the longer times can be accounted for by the relatively large ratio of the source size to the size of the thermocouple box used in the experimental setup, since an infinite plate size was assumed for the theoretical calculations. An important experimental parameter that could be investigated is the effect of an airstream on the heat flow to the inner surface. This factor should considerably reduce the hot-spot temperatures measured.

In the curves shown in figure 9 the reference temperature θ may be taken as the temperature of the molten aluminum; thus, in the experimental case, the hot-spot temperature rises to about 530° F in about 30 milliseconds and decays to one-half value in 0.4 second from $t = 0$. As the tank wall thickness decreases, the inner-surface peak temperatures will increase until the thickness at which puncture occurs is reached. While the results of the sample fuel-tank tests show that puncture is the most important factor in causing fuel ignition, it would be of interest to determine the transient temperature-time impulse curves required for ignition of common fuels used in aircraft, as discussed in the following section.

Fuel-Tank Explosion Studies

To determine the specific conditions under which fuels can be ignited, 6-inch-cubic aluminum tanks partly filled with aviation gasoline or JP-4 were struck with 75 high-current discharges over a temperature range from 32° to 90° F. In formulating the problem, consideration was given by NACA and LRI to the following possible mechanisms for igniting fuels:

- (1) The fuel is ignited by a hot spot on the wall of an unpunctured tank.

(2) The discharge penetrates the tank and appears on the inside to produce the equivalent of spark ignition.

(3) An efflux of fuel-air mixture out of the puncture exposes the fuel to the lightning outside the tank. The fire then propagates through the puncture to the inside of the tank.

(4) Incandescent metal particles shower into the tank when the lightning strikes the wall.

Many lightning strokes to aircraft are swept over the surface of the aircraft, and frequently pitting occurs without actual puncture of the skin. It is of considerable interest, therefore, to determine whether hot spots on a fuel-tank wall due to lightning that does not puncture the wall could cause ignition. The temperature-time parameters pertinent to mechanism (1) were considered in the preceding section. The temperature-time graphs for an aluminum tank wall 1/8 inch thick (fig. 9(b)) indicate that for the experimental 20-coulomb discharge the inner-wall temperature will exceed 480° F for only about 60 milliseconds. This is approximately the slow spontaneous-ignition temperature of kerosene or JP-4 and corresponds to about four-tenths of the outer aluminum wall melting temperature of 1,216° F. The investigations of reference 1 show that ignition of methane-air and hydrogen-air mixtures in 40 milliseconds by hot wires requires temperatures estimated to exceed 2,400° F and possibly as high as 3,500° F, an increase of 5 times the slow spontaneous-ignition temperatures.

The experimental discharges were 20 milliseconds in duration. Strokes to the side wall of an exposed aircraft fuel tank should not hang on to any one point on a smooth surface for longer than 10 milliseconds because of the aircraft motion. Pit marks from strokes to aircraft that have been swept over a wing or fuselage surface are generally spaced from a few inches to a few feet apart. Assuming an aircraft velocity of 140 mph or 205 feet per second, this would correspond to a maximum time duration at any single point of 2 feet/205 feet per second = 9.8 milliseconds. Thus in view of the short stroke durations, windstream cooling effects, and resultant lower expected fuel-tank wall temperatures, it seems improbable that strokes that do not puncture should ignite aircraft fuels. It should be emphasized, of course, that this applies only to strokes that are swept and not, for example, to strokes that hang on to the trailing edge of a section and may easily last for periods approaching 1 second. Additional data on the short-time ignition temperature characteristics of aircraft fuels are required for greater assurance on this point.

From the preceding considerations the question naturally arises whether, for short-duration stroke energies slightly below the level required to puncture the tank wall, the metal will be nearly molten and the temperature be high enough to ignite the fuel. It is conceivable that, while the temperatures would greatly exceed the slow spontaneous-combustion temperature of the fuel, the time duration would be too short for ignition. In order to investigate this possibility, a series of tests was made on the 6-inch-cubic tanks of 0.040- and 0.064-inch thickness using stroke energies at approximately the puncture energy level, in which 53 discharges were fired to the series of tanks. The strokes punctured the tanks 16 times and failed to puncture them 37 times. In every case a puncture was accompanied by an explosion, and in every case but one a failure to puncture produced no explosion. The results of these tests were verified in succeeding tests on other phases of the problem. The one explosion that occurred without fuel-tank puncture was due to a discharge that accidentally struck the tank a few inches from a vent hole and possibly threw a spark into or near the opening.

A photographic sequence of fuel-tank ignition by an artificial-lightning discharge that punctured the tank wall is shown in figure 10, as recorded by a Fastax camera. The discharge contacted the rear of the tank, burned a hole through it, and ignited the mixture within a few milliseconds. A similar sequence is shown in figure 11 for a 300-mph wind-stream and with the electrode on top of the tank. Although a longer time was required for puncture of the second tank, the explosion flamefront velocity appears to be about the same for each case, as does the time required for the tanks to explode, which is less than 40 milliseconds. The mixtures in each tank were fairly close to optimum.

A sketch of the test arrangement for these fuel-tank studies is shown in figure 12. The fuel-air ratios were held in the explosive range during the tests as recorded by the NACA fuel-air analyzer. Temperatures of the fuel were controlled and recorded. The fuel-air ratios were controlled by bleeding air slowly into the tank until the proper mixture was obtained. Owing to the 40-second delay of the mixture analyzer in recording the fuel-air mixture, the mixture rates of change were kept low to minimize interpolation errors. The tanks were normally filled not more than 1/4 inch with fuel. Examination of the areas where the discharges occurred without puncture invariably disclosed fine cracks, probably due to the local heating and cooling, that extended through the tanks and permitted fuel to leak out. These are not considered to be serious, since they probably occurred after the metal had cooled and no external fires occurred. A photomicrograph of one of these areas is shown in figure 13.

Next, a series of tanks was punctured by heavy discharges while the mixture was varied. In nearly every case the tank exploded over a range

of mixtures from 0 to 100 and 100 to 160 extrapolated beyond the normal analyzer range of 0 to 100 parts per thousand. The analyzer was examined to determine whether the indications were incorrect, but pure air produced a reading of zero and warm fuel in the tank drove the analyzer off scale past 100. In addition, explosion pressures were measured for a range of mixtures. The pressures were higher inside the 60 to 80 range, generally bursting the tanks and roughly confirming the accuracy of the mixture analyzer. Only JP-4 was used in investigating hot-spot ignition of fuels, since it was conveniently in the explosive range at room temperature and also had a low spontaneous-ignition temperature; but both JP-4 and 100/130-grade aviation gasoline were used in the pressure measurements. Explosion of the tanks at extremely lean mixtures was attributed to nonequilibrium conditions: a lean mixture in the space over the fuel which the analyzer sampled, and a combustible mixture at the fuel-air boundary ignited by spark showers from the puncture. Photographs of spark showers from punctured aluminum sheets are shown in figure 14.

To measure overrich mixtures, which were not measured by the mixture analyzer, specific mixtures were obtained by allowing partially filled fuel tanks to come to equilibria at particular temperatures. For example, tanks with gasoline held for 5 minutes at 80° F were assumed to contain an extremely overrich mixture. Puncturing discharges did not cause an explosion, but a fire was started at the puncture hole that continued for 1 minute until put out by an extinguisher. Gasoline held at 32° F did not explode; however, JP-4 did explode at this temperature. Discharges below the liquid level produced fires at the puncture point but no explosions.

In analyzing the sequence of explosion experiments, the mechanisms listed at the beginning of this section that appear the most likely are the direct puncture of fuel-tank walls followed by (2) explosion and (3) external fires. Ignition by (1) hot spots seems improbable on the basis of the investigations of the preceding section, and (4) the showering of sparks into a tank with no puncture would be even more improbable, since the wall would probably not be hot enough to spark if it would not ignite the fuel.

Although initial measurements indicated that lightning-discharge currents because of their great energies were capable of igniting fuels over a greater range of mixtures than would be possible with spark ignition, particularly with lean mixtures, basically the investigations showed general agreement with existing flammability data. Overrich mixtures were not exploded, but external fires occurred at the puncture holes. Lean mixtures were ignited, but ignition of lean mixtures due to mists (e.g., from agitation) has been generally recognized. The explosion hazard is considered to be more serious than the fire hazard. External fires can occur whenever a fuel-tank wall is punctured, with any

fuel; but aircraft fires, though a serious matter, can often be controlled. Because of the low flame-propagation rates under any but extreme conditions, these fires are sometimes extinguished by the windstream, sometimes by special maneuvers of the aircraft, or by carbon dioxide systems. Explosions of fuel tanks, on the other hand, can result in severe structural damage or loss of the aircraft. For this reason, the most significant information regarding the degree of hazard is probably the relation of the flammability ranges of various fuels to the temperatures at which most lightning strokes to aircraft occur.

LTRI records show that, for 103 lightning strokes to aircraft on domestic flights, 93 percent occurred within 10° C of the freezing temperature, or from 14° F to 50° F. This temperature range includes the flammability range of JP-4, is below the lean limit for JP-5, JP-1, or kerosene, and includes the rich region for JP-3 and the extreme overrich range for aviation gasoline. Thus, the safest fuel with respect to lightning hazards would be aviation gasoline, with JP-4 the worst. The safety of JP-1 and JP-5 appears to depend on how readily they form mists; also, the precise mechanism by which LTRI obtained explosions of lean mixtures needs further clarification.

The experimental results have been confirmed by recent flight-damage reports of lightning strokes to aircraft fuel tanks. Holes in tanks from lightning, a gasoline fire in one tank that burned for 15 minutes, as well as an explosion of a jet aircraft wingtip fuel tank just after it had been jettisoned have all been reported within the last nine months. Thus, no other conclusion can be reached but that jet fuels, JP-4 in particular, present a much more severe explosion hazard than aviation gasoline, which has shown a good safety record to date.

Metal Erosion from Lightning Discharges

In order to determine the energies and charge transfers required to puncture various thicknesses of aircraft aluminum alloys, 75 high-current laboratory discharges with and without windstream were fired to test samples of three alloys commonly used for fuel-tank walls. The alloys were 2024-T3, 3003-H14, and 6061-T3 in 0.020-, 0.040-, 0.064-, 0.081- and 0.102-inch thicknesses. A tapered double-wall construction was used with the two thinnest samples to examine the relative merits of double-wall construction against single walls of equivalent thickness. The walls were spaced $1/8$, $1/4$, $1/2$, and 1 or more inches apart. The artificial-lightning discharges discussed in the APPARATUS AND PROCEDURE section were used together to produce a single standard combined discharge. As discussed previously, the predominant factor in puncture of aluminum tank walls is the charge transfer of the long-duration low currents and of the intermediate currents; however, since the metal erosion for a given

charge transfer is modified to some extent by the current magnitude, relating metal erosion to charge transfer is of course an approximation. Holes burned in the ends of wingtip tank tailcones by natural lightning (fig. 15(a)) can be compared with holes produced in aluminum sheet by laboratory discharges (fig. 15(b)). In the 30-coulomb laboratory discharges, the hole size varies considerably with the current magnitude. The standard discharge that LTRI has adopted as representative of strokes to aircraft will duplicate most of the damage done to aircraft, but it should be noted that occasionally there will be strokes that may exceed 200 coulombs by a considerable amount.

The combined artificial-lightning discharges fired to the various alloys produced punctures in all thicknesses through 0.064 inch but in none of the alloys 0.081 inch or over with the exception of some in the windstream tests in which the vibration caused the arcing electrode actually to contact the aluminum sheet. Owing to difficulty in maintaining the arc with the airflow present, the windstream tests were not considered to be representative of natural-lightning discharges under windstream conditions, since the arc was confined to one point, but they did provide valuable information regarding cooling and other secondary effects. Use of higher potential long-duration current sources and a larger wind-tunnel section would permit longer arcs that would be more representative of natural-lightning discharges to aircraft; however, this would not produce conclusive information as to hazard, because the variation in natural-lightning discharges is so great that no reasonable value of stroke magnitude can be selected as a "probable expected maximum." Discoloration and heat distortion of the metal, noted when no windstream was used, were almost totally absent with the windstream, indicating an extensive cooling effect; the metal erosion was clean and slightly more severe, apparently because of the plentiful supply of oxygen. It is interesting to note that flight-damage reports have mentioned similar effects; for example, one reported that "burned spots on the tank resembling momentary touches by a cutting torch clearly indicate that damage was done by a lightning strike." In tests of double-wall sections, 0.040-inch aluminum had to be separated 1/4 inch to be equivalent to one 0.031-inch wall, and double-wall sections of 0.020-inch aluminum were punctured when separated over 1 1/2 inches. Photographs of the effect of the discharges on aluminum sheet are shown in figure 16.

The knowledge of the sweeping effect of the aircraft motion in reducing the localized pitting by distributing the stroke energy over a large area had earlier permitted some optimism regarding the need for lightning protection of fuel-tank side walls. As an example, the effect of aircraft motion in sweeping natural-lightning discharges is illustrated in figures 17 and 18. In the tip tank tailcone shown in figure 17, two small pit marks are shown on the side wall, but a moderate-sized hole may be seen at the rear where the stroke could hang on for an extended period.

Holes in 0.020-inch aircraft skin are shown in figure 18. The stroke apparently struck a long wire antenna attached to a VHF mast located at the left and was conducted along the wire and down the mast to the base where it burned a large hole as the aircraft moved forward. At this point it probably broke away from the mast to burn the series of small holes in the thin aluminum sheet.

Although the standard laboratory discharges considered to be representative for aircraft struck in flight did not puncture aluminum sheet 0.081 inch thick, it is felt that complete reliance on this wall thickness for protection from natural strokes to aircraft would not be justified because of the occasional strokes that are known to contain considerably greater charge transfers than the 200 coulombs used in this sequence of tests. Although the probability of such a discharge to a fuel-tank side wall is small, the consequences are so serious that additional precautions are felt to be necessary. Such additional precautions could include ribs on tip tanks, location of tanks away from the immediate tip area where lightning strokes are most likely to occur, use of fuel-tank liners in critical areas near the wingtip, or thickening of the wing and use of lightning diverters to divert strokes from critical areas such as fuel vents.

Lightning Strike Data Pertinent to Fuel-Tank Hazards

In the preceding sections of this report, references have been made to MITI data on lightning strokes to aircraft. Pertinent sections of these data are presented in figures 19 to 21. The distribution of lightning strokes with temperature for domestic airline flights is shown in figure 19. Over 90 percent of the strokes for which the temperatures have been recorded occurred within the range of $+10^{\circ}$ to -10° C, and 65 percent of the strokes occurred in the range of 0° to $+5^{\circ}$ C. This is not surprising in view of the most widely accepted theory of thunderstorm electrical charge formation by separation across the freezing level.

It has been suggested that the strokes are grouped about the freezing level because it happens to correspond to the most common flight altitudes. The MITI data on the distribution of strokes with altitude (fig. 20) disproves this theory. These data, which show that the strokes occurred at no particular altitudes, indicate that the probability that an aircraft will be struck is related to its proximity to the freezing level. Most strokes occurred at altitudes of 6,000 feet or over where the cloud-to-cloud discharges of low-current magnitudes and high-charge transfers are more common. This is in agreement with the analysis of lightning-damaged aircraft parts, which shows that a substantial proportion of such parts have passed high-charge transfers.

The analysis of the distribution of damage presented in figure 21 shows that a substantial percentage of strokes occurred to the wings, which in modern aircraft are the principal fuel-storage locations. Figure 21 is based on 431 incidents, which is considerably more than for figures 19 and 20 because most stroke reports received record the part struck but some do not record the temperature or altitude.

Model Studies of Most Likely Points of Lightning Strike

Flight-damage report statistics are a great aid in evaluating hazards because they provide general information as to the most likely points for lightning to strike. Model studies are also effective for studying critical areas of aircraft in some detail. Although extensive model studies were not contemplated in this investigation, preliminary studies in another investigation indicate that, for the wings, the most vulnerable areas are the tip areas and the areas behind the propellers on propeller-driven aircraft. Direct strokes to the wingtip and strokes to the propellers that can be swept back by the airstream over either the top or bottom of the wing are most probable. Two-million-volt discharges to model aircraft are shown in figures 22 to 24. Discharges to two model aircraft (figs. 22 and 23) illustrate the high probability of vertical strokes to the vertical fin. Strokes to the model from various angles permit evaluation of the most probable points of lightning strike; and, by use of intermediate-sized model sections, somewhat more detailed information may be obtained. This information, as related to the airflow direction, permits fair estimates of protection in these critical areas.

The streamer on the wingtip of the aircraft in figure 23 illustrates effectively the mechanism of lightning-stroke approach to an aircraft. When the advancing step leader of a lightning stroke nears the aircraft, an intense electric field is set up and corona streamers produced by this field leave the aircraft from high-gradient points to meet the step leader. The step leader contacts the aircraft through one or more of the streamers and raises the aircraft potential to a value sufficient to produce streamers off the opposite aircraft extremities. These streamers form the step leaders for further advance of the stroke past the aircraft. The formation of streamers is determined by the extent of the field distortion about the aircraft. Their formation near the aircraft is probably affected by the pressure variations caused by local turbulence; however, this has not been definitely established.

Electrolytic tank plots of the electric-field configuration about the aircraft model also give a clear picture of the extent of the field distortion, which is only indirectly illustrated by photographs of strokes to a model. An electrolytic tank plot of the electric field about the model of figure 24 is shown in figure 25 just before and after a lightning stroke contacts the aircraft. The extent and intensity of the

electric field are maximum about the nose and wingtip fuel tanks, as indicated by the spacing and shape of the equipotential lines. This is in agreement with the high-voltage studies, which showed about equal probability for strokes to the aircraft nose or front of the wingtip tank (fig. 24). More extensive studies of this type would be valuable in general development of protective measures, especially in studies of particular areas of specific aircraft.

CONCLUDING REMARKS

This experimental investigation of the various mechanisms of fuel-tank explosion due to lightning strokes reveals that there is a primary hazard whenever there is direct puncture of the fuel-tank wall but that the ignition of fuel by hot spots on tank walls without puncture is unlikely. Punctures of the fuel-tank walls by artificial-lightning discharges under various environmental conditions produced explosions of fuel mixtures varying from excessively lean to full-rich. When a hole was not actually made in the inner fuel-tank wall, temperatures exceeded one-half the exterior molten-aluminum temperatures only for brief periods, probably insufficient to cause explosion of aircraft fuels. Additional data on the short-time ignition temperature characteristics of aircraft fuels are required for complete assurance on this point.

LTRI data on lightning strikes to aircraft show that 90 percent of the strikes recorded have been in the temperature range from -10° to $+10^{\circ}$ C, where many of the jet fuels are explosive but where aviation gasoline is overrich. Also, 10 percent of the strokes recorded have been to the wing areas, which for modern aircraft are the principal fuel-storage areas. These results indicate that protective measures are needed, particularly for jet fuels and to a lesser extent for aviation gasoline, which, although not explosive in the temperature ranges at which most lightning strokes occur, can be ignited to produce external fires.

Fuel-tank aluminum alloys 0.081 inch or thicker were not punctured by discharges representative of natural-lightning discharges to aircraft. However, reliance for protection from aircraft lightning strokes solely on increasing tank thicknesses to 0.081 inch is not necessarily a solution, since occasional strokes are known to contain considerably greater charge transfers than the 200 coulombs used in the experimental studies. Although the probability of such strokes to critical areas is small, the consequences - possible fires or explosions - are so serious that additional precautions are felt to be necessary.

While protection-system development is beyond the scope of this report, the following suggestions can be made for development of protective measures:

- (1) Some thickening of specific tank areas or use of external fins or ribs to be located on the basis of the probability of discharge paths may considerably reduce the hazard.
- (2) Several types of fuel-tank liners may be used adjacent to the most probable discharge path.
- (3) Lightning-diverter rods may be used to divert strokes from critical areas such as fuel vents.
- (4) Blowout panels may be used in tanks near the wingtip to reduce the stress on the main wing structure due to a tank explosion near the tip.
- (5) Plastic wingtip tanks, though considered quite hazardous without specific protective design, might be made safer than conventional metal tanks.

Lightning and Transients Research Institute,
Minneapolis, Minn., February 1, 1957.