


SPECIAL AIRWORTHINESS INFORMATION BULLETIN



U.S. Department
of Transportation

**Federal Aviation
Administration**

CE-03-05
November 7, 2002

Aircraft Certification Service
Washington, DC

We post SAIBs on the internet at "av-info.faa.gov"

This is information only. Recommendations are not mandatory.

Introduction

This Special Airworthiness Information Bulletin (SAIB) advises you, owners and operators of Grob Luft-und Raumfahrt G115EG model airplanes, of issuance of Grob Mandatory Service Bulletin (MSB) MSB 1078-135.

Background

The FAA conducted a review of specified of Grob G115EG airplane service bulletin. The purpose of the review was to evaluate each service bulletin to determine the continued airworthiness safety aspect. Options included: Mandated compliance by initiation of a FAA Airworthiness Directive (AD), various forms of notices, or no further action required.

Recommendations

The service bulletin identified in this document is not considered appropriate for AD action at this time; however, the FAA strongly suggests that all owners/operators of the Grob G115EG series airplanes review their compliance with the service bulletin listed below.

Grob G115EG Airplane Service Bulletin Number	MODEL	DATE	TITLE
MSB 1078-135	G115EG	September 27, 2002	Electrical Load Distribution

The Service Bulletin Can Be Obtained From

Manager, Airworthiness/Certification, Grob-Werke, Luft-und Raumfahrt, Lettenbachstrasse 9, D-86874 Tussenhausen-Mattsies, Germany; Phone: (011) 49 82 68 9 98 0; Fax: (011) 49 82 68 9 98 114; www.grob-aerospace.de

For Further Information Contact

Karl M. Schletzbaum, Aerospace Engineer, FAA, Project Support Branch (ACE-112), Small Airplane Directorate, 901 Locust Street, Room 301, Kansas City, Missouri 64106; telephone: (816) 329-4146; fax: (816) 329-4090; email: karl.schletzbaum@faa.gov