


SPECIAL AIRWORTHINESS INFORMATION BULLETIN

Aircraft Certification Service
Washington, DC



U.S. Department
of Transportation

**Federal Aviation
Administration**

CE-04-67
May 6, 2004

www.faa.gov/certification/aircraft

This is information only. Recommendations aren't mandatory.

Introduction

This Special Airworthiness Information Bulletin informs you, owners and operators of **Learjet (Gates) model 35 and 36**, of the availability of Bombardier Aerospace Recommended Service Bulletin (SB) 35/36-35-4.

Background

We have received reports, including a safety recommendation from the National Transportation Safety Board, that verifying the ON-OFF position of the oxygen bottle regulator is difficult to ascertain visually on the Learjet 35 and 36. Bombardier has re-designed the ON-OFF placards for this regulator and their SB 35/36-35-4 provides instructions to install the new placards.

Recommendation

We highly recommend that you install the newly designed oxygen bottle regulator ON-OFF placards as instructed in Bombardier Aerospace Service Bulletin SB 35/36-35-4.

For Further Information Contact

Michael Imbler, Senior Aero Engineer; FAA Wichita Aircraft Certification Office, 1801 Airport Rd, Room 100, Wichita, Kansas, 67209; phone: (316) 946-4147; fax: (316) 946-4107; email: michael.imbler@faa.gov

For Service Bulletin Information Contact

Mr. Randy Williams, phone: (316) 946-2725; email: randy.williams@Learjet.com; Learjet, Inc., 7761 West Kellogg, Building 11, Mail Stop 71, Wichita, KS 67209.