

BE AWARE!

Inset A:

J Taxiway at intersection with taxiway B



Inset B:

H Taxiway at intersection with taxiway B.



Airport Operations: (860) 445-8549
Air Traffic Control: (860) 445-7019
Hours of Operation: Airport-24 hours,
Tower 0700 to 2200 Local Time
Latitude: 41° 19.8' N
Longitude: 072° 02.7' W
Airfield Elevation: 10 feet.
Variation: 15° West
From City of Groton 3 miles SE
Sectional Chart New York
Control Tower: Yes
ARTCC: Boston Center --124.85
When departure inop.
FSS: Bridgeport 800-wx-brief
NOTAM Facility: Bridgeport
Wind Indicator: Yes
Beacon: Yes
Fire and Rescue: Yes
Airline Operations: Yes
Customs: Yes Four hour prior notice
required (860-240-4306) (860-442-7123)
UNICOM: 122.95-131.75
CTAF 125.6
ATIS: 127.0
Ground: 121.65
Tower: 125.6
Clearance Delivery: 118.55 Providence
clearance after tower closed
Approach Control: 118.45-125.75 When
closed, BOS Center 124.85
VOR: TMU 110.85 On field
RCO: Bridgeport 122.1T 110.85R
Emergency: 121.5

Airport Incursion Information




Groton/New London Connecticut (GON)



September 2004

Federal Aviation Administration
New England Region Runway Safety Program
<http://www.faa.gov/region/anc/rsपो>

Orig 04050
AIRPORT DIAGRAM



AIRPORT DIAGRAM
 Orig 04050

GROTON-NEW LONDON (GON)
 GROTON (NEW LONDON), CONNECTICUT

GROTON (NEW LONDON), CONNECTICUT
 GROTON-NEW LONDON (GON)

HIGH ALERT INTERSECTIONS

- 1.** When leaving runway 33/15 at taxiway J exercise caution for other aircraft. After crossing the hold short position marking you will be on taxiway B.
- 2.** When leaving runway 33/15 at taxiway H exercise caution for other aircraft. After crossing the hold short position marking you will be on taxiway B.
- 3.** When exiting runway 33 at taxiway A or J do not taxi past B taxiway. Taxiway A and taxiway J extend from runway 33/15 to taxiway B. The area beyond taxiway B is part of the military ramp.
- 4.** Avoid taxi on the vehicle lane (white markings) that extends from the main ramp to the northeast ramp.
- 5.** Use caution, Taxi slowly on taxiway C. Pooling of water occurs on C between runway 33 and taxiway B.