

Flight Procedures Cover Page	Task Action: Abbreviated Amendment	Task Type: IAP	Estimated Chart Date: 07/09/2026	APWS Task ID: 5D714A44DFCE4D3F986153CB4BA5E81C	APWS Project ID: A6ACBF77CF4844DA81587FC514A5BD10
Procedure: RNAV (GPS) RWY 36 ORIG-E		Enroute: NO	Specialist: Smart, Phillip		Agreement Number:
Airport ID: 2F7			Airport City: COMMERCE		State: TX
Facility ID:	Facility Type:	Flight Inspection Remark Type:			
Procedure Comments: CLEARs T-NOTAM FDC 5/2820. Processed IAW Technical Support Group (AJF-17) Memo dated 07/07/2021 Guidance for Procedural Changes Requiring Flight Inspection/Validation. CONTACT CASEY HILL, MANAGER AJV-A431, 405.954.0624. QUALITY 23 CHECKED QUALITY 13 CHECKED					

APP CRS	Rwy Ldg	3907
359°	TDZE	512
	Apt Elev	516

old

RNAV (GPS) RWY 36

COMMERCE MUNI (2F7)

RNP APCH.	MISSED APPROACH: Climb to 3000 direct CEKIR and hold.
▼ ▲ NA	Use Greenville altimeter setting, when not received, use Sulphur Springs altimeter setting and increase all MDAs 20 feet. Rwy 36 helicopter visibility reduction below ¾ SM NA.

GVT AWOS-3 133.425	FORT WORTH CENTER 132.025 317.75	CTAF 122.9
-----------------------	-------------------------------------	---------------

