

[Print](#)

Project Name: BWD

Project Reason: KBWD LOC RWY 17 incorrect radial R-356 should read R-352 within missed app instructions per flight inspection OP-06-077-24 (03/15/2025). KBWD VOR RWY 17 incorrect aircraft category (Cat A should read Cat C) within inoperative ALS instructions.

Last Updated By: PHILLIP SMART

Last Updated At: 2025-03-17 15:29:00.230355

Status: Verified

5/2428

!FDC X/XXXX BWD IAP BROWNWOOD RGNL, BROWNWOOD, TX. LOC RWY 17, AMDT 5... CHANGED MISSED APPROACH INSTRUCTIONS TO READ:
CLIMBING RIGHT TURN TO 4000 ON HEADING 021 AND ON BWD VOR/DME R-352 TO ELISE INT/BWD 10 DME AND HOLD. THIS IS LOC RWY 17, AMDT 5A.
2503171528-PERM

Digitally signed by
ROBERT G HAMILTON
Apr 28, 2025

QUALITY
32
CHECKED