## Federal Aviation Administration

### **Transmittal Letter 19-13**

#### MAY 3, 2019

## PREPARED BY THE AERONAUTICAL INFORMATION GROUP, AJV-53 (AVAILABLE ON THE WEB AT HTTP://NFDC.FAA.GOV)

### The enclosed Standard Instrument Approach Procedures, Departure Procedures/Takeoff Minimums and Fix Actions are effective as indicated.

By amending: §97.23 VOR, VOR/DME, VOR or TACAN, and VOR/DME or TACAN; §97.25 LOC, LOC/DME, LDA, LDA/DME, SDF, SDF/DME; §97.27 NDB, NDB/DME; §97.29 ILS, ILS/DME, MLS, MLS/DME, MLS/RNAV; §97.31 RADAR SIAPs; §97.33 RNAV SIAPs; and §97.35 COPTER SIAPs, Identified as follows: EFFECTIVE UPON PUBLICATION						
AIRAC DATE	STATE	CITY	AIRPORT	FDC NUMBER	FDC DATE	SUBJECT
6/20/2019	NJ	Teterboro	Teterboro	9/6879	4/16/2019	VOR/DME-B, Amdt 2E

# AIRAC Date: 20 JUNE 2019

FDC 9/6879 TEB IAP TETERBORO, Teterboro, NJ. VOR/DME-B, AMDT 2E... CHANGE MISSED APPROACH TO READ: CLIMBING RIGHT TURN TO 2500 ON TEB R-335 TO PATRN INT AND HOLD. DELETE NOTE: CIRCLING RWY 24 NA AT NIGHT. CHART NOTE: WHEN CIRCLING TO RWY 24 AT NIGHT, OPERATIONAL VGSI REQUIRED, REMAIN ON OR ABOVE VGSI GLIDEPATH UNTIL THRESHOLD. THIS IS VOR/DME-B, AMDT 2F. 1904031929-PERM