

## FINAL COMMENT LOG

Originating Office: <b>FTW-AEG</b>		Document Title/Description: <b>MMEL AS-350 Rev 7, Airbus Helicopters, AS350C, AS350D, AS350D1, AS350B, AS350B1, AS350B2, AS350BA, AS350B3 (TCDS H9EU)</b>			POC and Phone Number: <b>Philip Whiting, 817-222-5299</b>		Suspense Date: <b>04/26/2021</b>	
<b>Commenter Name and Organization</b>	<b>Date</b>	<b>Page #</b>	<b>Line, Para, or Item #</b>	<b>Comment</b>	<b>Recommendation</b>	<b>Response</b>		
David Ryon AFS-210 for AFS-240	10/27/20	XIII	3246-01 Snow Skis	Question: In Procedure, should "Skids" be "skis"?	Change to skis if appropriate.	Changed "skids" to "skis" for the referenced procedure.		
David Ryon AFS-210 for AFS-240	11/10/20	25-3	2562-01 Emergency Locator Transmitter	Policy: Fixed ELTs, second A Repair Category should have a placard requirement for missing ELT (PL 120)	Suggest Change to:  (M) May be missing provided: a) Placard stating "ELT not installed" is placed in view of the pilot, and b) Repairs are made within 90 days.	As per PL 120, changed to:  (M) May be missing provided: c) Placard stating "ELT not installed" is placed in view of the pilot, and d) Repairs are made within 90 days.		
David Ryon AFS-210 for AFS-240	10/28/20	32-1	3246-01 Snow Skis	Question: In Remarks or Exceptions, should "Skids" be "skis"?	Change to skis if appropriate.	Changed to skis.		
David Ryon AFS-210 for AFS-240	11/10/20	23-2	2311-02 Communications Systems (VHF and UHF)	Question: Should Frequency selector knob and frequency indicator each show two required for dispatch per PL 95 or is the dash more appropriate?	Change to match PL if appropriate.	No change made. The PL allows the relief to be customized to each aircraft type.		
David Ryon AFS-210 for AFS-240	11/10/20	23-1	2310-01 High Frequency Communication System (HF)	Policy: Remarks for d) should state d) Alternate procedures are established and used (PL 106).	Add "and used." to proviso d).	As per PL 106, added "and used" to proviso d).		
David Ryon AFS-210 for AFS-240	11/10/20	25-3	2562-01 Emergency Locator Transmitter	Policy: Fixed ELT, second D Repair Category should not reference inoperative (PL 120).	Suggest Change to:  Any in excess of those required by 14 CFR may be missing.	As per PL 120, deleted the reference to "inoperative."		
David Ryon AFS-210 for AFS-240	11/10/20	25-4	2562-01 Emergency Locator Transmitter	Policy: ELT Aural Light should be listed as ELT Aural Alarm to match PL 120.	Change to "Aural Alarm" if appropriate (unless the intent was Aural Alarm Indicator Light?)	As per PL 120, changed "Aural Light" to the correct title "Aural Alarm."		

<b>Commenter Name and Organization</b>	<b>Date</b>	<b>Page #</b>	<b>Line, Para, or Item #</b>	<b>Comment</b>	<b>Recommendation</b>	<b>Response</b>
John Drago AFS-820 330-648-3887	11/18/20	23-3	2370-03	Cockpit Voice Recorder (CVR), category A item has no repair interval specified.	Specify repair interval.	No change. The relief is depicted as an exact match to PL 29. PI 29 does not include the option for the FOEB chair to make modifications.
John Drago AFS-820 330-648-3887	11/18/20	31-2	3130-03	Flight Data Recorder (FDR) System, category A item has no repair interval specified.	Specify repair interval.	No change.
Philip Whiting FTW AEG	01/22/21	31-2	3130-03	Missing the policy reference.	Add (PL-87) below the sequence number.	Added (PL-87) below the sequence number.