



**FAA
Airports**

Errata Sheet for Advisory Circular (AC) 150/5200-30D, Airport Field Condition Assessments and Winter Operations Safety

Last Update: 11/14/2016

This errata sheet logs content errors and required updates identified after the Advisory Circular was signed on July 29, 2016. These errors have been corrected in the consolidated PDF version of the AC available on the FAA website.

#	Description of Correction	Location in Document	Rationale	Date Error Corrected
1	The listed decelerometer, VERICOM VC3000 RFM DECELEROMETER, needs to be update with the current FAA approved decelerometer VERICOM VC4000 RFM DECELEROMETER. Please note that FAA approved this new decelerometer on October 26, 2010.	Appendix D	The October 26, 2010 letter from AAS-100 to the vendor indicated that this would be corrected when the AC was updated. However, this correction did not make the latest version of the AC issued on 7/29/2016.	