



**FAA  
Airports**

## **Errata Sheet for Advisory Circular AC 150/5345-39E, FAA Specification L-853, Runway and Taxiway Retroreflective Markers, Last Update: 10/20/2021**

This errata sheet logs content errors and required updates identified after the Advisory Circular was signed on October 12, 2021. These errors have been corrected in the consolidated PDF version of the AC available on the FAA website.

<b>#</b>	<b>Description of Correction</b>	<b>Location in Document</b>	<b>Rationale</b>	<b>Date Error Corrected</b>
1	Corrects numbered list in the Principal Changes paragraph.	Coversheet, par. 5, p. ii	The list numbering should have restarted with "1" rather than continuing the numbering from the previous list.	10/20/2021
2	Corrects reference error in list item 1. Text should read "Paragraph 3.1.1.2.3, item 5".	Coversheet, par. 5, item 1 (previously 5), p. ii	The reference was incorrect and resulted in an error in the PDF.	10/20/2021
3	Corrects the reference to "Paragraph 3.4.2.2, item 3" to read "moved to Paragraph 3.4.2".	Coversheet, par. 5, item 2 (previously 6), p. ii	The updated paragraph was moved. Item 2 should have referenced the new location.	10/20/2021