



**FAA  
Airports**

## **Errata Sheet for Advisory Circular (AC) 150/5345-44K, Specification for Runway and Taxiway Signs**

*Last Update: 1/14/2022*

This errata sheet logs content errors and required updates identified after the Advisory Circular was signed on October 8, 2015. These errors have been corrected in the consolidated PDF version of the AC available on the FAA website.

<b>#</b>	<b>Description of Correction</b>	<b>Location in Document</b>	<b>Rationale</b>	<b>Date Error Corrected</b>
1	Changed text from “The horizontal spacing/separation distance between message elements in a sign array within a common continuous housing (See Figure 11 for an example of a sign array) must be between at least 3 inches (76 mm) (accounting for any applicable minimum in Table 10) and must not exceed 12 inches (305mm) for a Size 1, 14 inches (356 mm) for a Size 2 and 16 inches (406 mm) for a Size 3 sign” to “The horizontal spacing/separation distance between message elements in a sign array within a common continuous housing (See Figure 11 for an example of a sign	Par. 3.2.5.2b	The previous language was interpreted to be in conflict with Table 10 of the document. The revised language resolves this conflict.	1/14/2021

#	Description of Correction	Location in Document	Rationale	Date Error Corrected
	array) must be between at least <b>the applicable minimum in Table 10</b> and must not exceed 12 inches (305mm) for a Size 1, 14 inches (356 mm) for a Size 2 and 16 inches (406 mm) for a Size 3 sign.”			