

Flight Procedures Cover Page	Task Action: Cancellation	Task Type: IAP	Estimated Chart Date: 10/02/2025	APWS Task ID: 0C9AB3193F3547AB8C891338A9BC25F8	APWS Project ID: 79B78387320A40498792F8FF511F61E8
Procedure: VOR RWY 23 AMDT 13C		Enroute: NO	Specialist: Darden, Michael		Agreement Number:
Airport ID: KGQQ			Airport City: GALION		State: OH
Facility ID:	Facility Type:	Flight Inspection Remark Type:			
Procedure Comments: Procedure Cancel, MFD VOR MON. Cancels FDC NOTAM 3/9652. CONTACT DAVID DANNER, AJV-A421, 405-954-5077. QUALITY 20 CHECKED					


VORTAC MFD	APP CRS	Rwy Idg	3504
108.8	224°	TDZE	1224
Chan 25		Apt Elev	1224

OLD

VOR RWY 23
GALLION MUNI (GQQ)

RADAR required for procedure entry.		MISSED APPROACH: Climbing left turn to 2900 direct MFD VORTAC and hold.
NA	Procedure NA at night. Use Mansfield altimeter setting; when not received, use Marion altimeter setting and increase all MDAs 40 feet, increase CUBYS fix minimums S-23 all Cats visibility 1/8 SM and Circling Cat C 1/4 SM. Rwy 23 helicopter visibility reduction below 1 SM NA.	

CLEVELAND APP CON ★	CLNC DEL	UNICOM
128.35 360.65	126.8	122.8 (CTAF) 0



ELEV 1224	TDZE 1224	2900 MFD	VGSI and descent angles not coincident (VGSI Angle 3.00/TCH 38).	MFD VORTAC	Remain within 10 NM
224°		CUBYS INT MFD 6.9	3.49° TCH 40	044°	3000
3504 175		MFD 8.9	*2000	224°	2900
2 NM		6.9 NM	* 2040 when using Marion altimeter setting.		
CATEGORY		A	B	C	D
S-23		2000-1 776 (800-1)	2000-1¼ 776 (800-1¼)	2000-2½ 776 (800-2½)	NA
CIRCLING		2000-1 776 (800-1)	2000-1¼ 776 (800-1¼)	2000-2½ 776 (800-2½)	NA
CUBYS FIX MINIMUMS					
S-23		1760-1	536 (600-1)	1760-1½ 536 (600-1½)	NA
CIRCLING		1800-1 576 (600-1)	1960-1 736 (800-1)	1960-2 736 (800-2)	NA

REIL Rwys 5 and 23 0
MIRL Rwy 5-23 0

FAF to MAP 8.9 NM					
Knots	60	90	120	150	180
Min:Sec	8:54	5:56	4:27	3:34	2:58