

Flight Procedures Cover Page	Task Action: Cancellation	Task Type: IAP	Estimated Chart Date: 10/29/2026	APWS Task ID: 289BA3FA3F7A4EB7B745C274BC92B04F	APWS Project ID: 99B85E1CBC4D4916B1F7DE86BFADD860
Procedure: VOR/DME OR GPS-A AMDT 7		Enroute: NO	Specialist: Hilley, Dustin		Agreement Number:
Airport ID: T15			Airport City: MARLIN		State: TX
Facility ID: ACT	Facility Type: VORTAC	Flight Inspection Remark Type:			
Procedure Comments: CANCLES NOTAM 5/2180. CONTACT CASEY HILL, AJV-A421, 405-954-0624					



OLD - CANCEL

MARLIN, TEXAS



AL-5854 (FAA)

25219

VOR ACT 115.3 Chan 100	APP CRS 123°	Rwy Ldg TDZE Apt Elev 411
--	------------------------	---

VOR/DME or GPS-A
MARLIN (T15)

 Use Waco Rgnl altimeter setting.  NA	MISSED APPROACH: Climbing left turn to 2800 via heading 270° and R-123 to MITRA/14 DME and hold.
WACO APP CON ★ 127.65 352.0	CTAF 122.9



MARLIN, TEXAS
Amdt 7 18MAY00

31°20'N-96°51'W

MARLIN (T15)
VOR/DME or GPS-A

SC-5, 14 MAY 2026 to 11 JUN 2026

SC-5, 14 MAY 2026 to 11 JUN 2026