

[Print](#)

Project Name: INT - REMOVAL OF NIGHT CIRC RESTRICTION ON RNAV15/33

Project Reason: CIRCLING WAS INCORRECTLY RESTRICTED TO RWY 4/22 ON THE RNAV 15 AND RNAV 33 APPROACHES. STATED REASON FOR RESTRICTION WAS BASIC RUNWAY MARKINGS. THERE IS NO CRITERIA TO RESTRICT CIRCLING BASED ON RUWNAY MARKINGS. RNAV 15 CHANGES: - DELETE CIRCLING RESTRICTION. - CHANGE PBN REQUIREMENTS NOTE FROM RNP APCH TO RNP APCH - GPS. - CHANGE BACKUP ALTIMETER NOTE TO MEET CURRENT CRITERIA. - CHANGE PLANVIEW NOTE AT FREON FROM " PROCEDURE NA FOR ARRIVALS AT FREON ON V222 NORTHEAST BOUND" TO "PROCEDURE NA FOR ARRIVALS AT FREON ON T414 NORTHEAST BOUND AND V45 NORTHBOUND." RNAV 33 CHANGES: -DELETE CIRCLING RESTRICTION - ADD PBN REQUIREMENTS NOTE. -CHANGE BACKUP ALTIMETER NOTE TO MEET CURRENT CRITERIA. -UPDATE CRITICAL TEMP BARO-VNAV NOTE. -UPDATE BACKUP ALTIMETER BARO-VNAV NA NOTE. - DELETE BACKUP ALTIMETER INOP ALS NOTE (NOT SUPPORTED BY CRITERIA). - DELETE *LNAV ONLY AND ASTERISK IN PROFILE AT EARLL - CHANGE ARRIVAL NA NOTE AT GSO TO CORRECT RADIALS

Last Updated By: Dustin Hardison

Last Updated At: 2026-07-08 18:19:54.511582

Status: Draft 6/4634

!FDC X/XXXX INT IAP SMITH REYNOLDS, WINSTON SALEM, NC. RNAV (GPS) RWY 15, AMDT 1D... DELETE NOTE: CIRCLING RWY 4, 22 NA AT NIGHT. CHANGE PBN REQUIREMENTS NOTE TO READ: RNP APCH - GPS. CHANGE NOTE TO READ: WHEN LOCAL ALTIMETER SETTING NOT RECEIVED, USE GSO ALTIMETER SETTING: INCREASE ALL MDAS 40 FEET AND CIRCLING VISIBILITY CATS C AND D 1/4 SM. CHANGE PLANVIEW NOTE TO READ: PROCEDURE NA FOR ARRIVALS AT FREON ON T414 NORTHEAST BOUND AND T45 NORTHBOUND. THIS IS RNAV (GPS) RWY 15, AMDT 1E. 2607081819-PERM

Digitally signed by

RAKE MCGRAW

Jul 10, 2026

