

Flight Procedures Cover Page	Task Action: Cancellation	Task Type: IAP	Estimated Chart Date: 10/29/2026	APWS Task ID: A2F75219CD3546FCA5F59888E139D645	APWS Project ID: ACEE0DFCAB2A4ADBA6DD0B9FA0871870
Procedure: VOR RWY 10 AMDT 4G		Enroute: NO	Specialist: Bruce, Richard		Agreement Number:
Airport ID: KLAL			Airport City: LAKELAND		State: FL
Facility ID: LAL	Facility Type: VORTAC	Flight Inspection Remark Type:			
Procedure Comments: CANCELS FDC NOTAM 5/1507. CONTACT RAKE MCGRAW, AJV-A422, (405) 954-8711. QUALITY 20 CHECKED					

VORTAC LAL 116.0 Chan 107	APP CRS 096°	Rwy Ldg 8500 TDZE 132 Apt Elev 142
---	------------------------	---

VOR RWY 10
LAKELAND LINDER INTL (LAL)

RADAR required for procedure entry. DME or RADAR required.		ALSf-2 	MISSED APPROACH: Climb to 1000 then climbing left turn to 2000 on heading 294° and on LAL VORTAC R-330 to PLUMY INT/ PIE 33.4 DME and hold.
 Circling NA to Rwys 8 and 26. Circling Rwy 28 NA at night. For inop ALS, increase S-10 Cat C/D visibility to 1½ SM; increase UDATE fix minimums S-10 Cat C/D visibility to RVR 6000.			

ATIS 118.025	TAMPA APP CON 120.65 290.3	LAKELAND TOWER 124.5 236.775	GND CON 121.4
------------------------	--------------------------------------	--	-------------------------

