| U.S. Department | 800 Independence Ave., S.W. |
|---|---|
| of Transportation | Washington, D.C. 20591 |

**Federal Aviation
Administration**

**Transmittal Letter 16-09**                                    **March 11, 2016**

**PREPARED BY THE AERONAUTICAL INFORMATION GROUP, AJV-53
(AVAILABLE ON THE WEB AT HTTP://NFDC.FAA.GOV)**

**The enclosed Standard Instrument Approach Procedures, Departure
Procedures/Takeoff Minimums and Fix Actions are effective as indicated.**

By amending: §97.23 VOR, VOR/DME, VOR or TACAN, and VOR/DME or TACAN; §97.25 LOC, LOC/DME, LDA, LDA/DME, SDF, SDF/DME; §97.27 NDB, NDB/DME; §97.29 ILS, ILS/DME, MLS, MLS/DME, MLS/RNAV; §97.31 RADAR SIAPs; §97.33 RNAV SIAPs; and §97.35 COPTER SIAPs,    Identified as follows:                 ...............................EFFECTIVE UPON PUBLICATION

| AIRAC DATE | STATE | CITY | AIRPORT | FDC NUMBER | FDC DATE | SUBJECT |
|---|---|---|---|---|---|---|
| 28-Apr-16 | CA | Oceanside | Oceanside Muni | 6/5020 | 02/22/16 | Takeoff Minimums and (Obstacle) DP, Amdt 4 |

## AIRAC Date: 28 APRIL 2016

FDC 6/5020 OKB ODP OCEANSIDE MUNI, OCEANSIDE, CA. TAKEOFF MINIMUMS AND (OBSTACLE) DEPARTURE PROCEDURES AMDT 4... CHANGE AIRPORT NAME TO READ BOB MAXWELL MEMORIAL AIRFIELD. THIS IS TAKEOFF MINIMUMS AND (OBSTACLE) DEPARTURE PROCEDURES, AMDT 4A. 1602171359-PERM