

LOC/DME I-GCS 109.9 Chan 36	APP CRS 290°	Rwy Ldg TDZE 56 Apt Elev 76
---	------------------------	---

ILS RWY 29 (SA CAT I & II)
PORTLAND INTL JETPORT (PWM)

T DME or RADAR required. DME required when Portland approach control closed. A Procedure NA when control tower closed. SA CAT I: Requires specific OPSPEC, MSPEC, or LOA approval and use of HUD to DH. SA CAT II: Reduced lighting requires specific OPSPEC, MSPEC, or LOA approval and use of Autoland or HUD to touchdown.	MALSR 	MISSED APPROACH: Climb to 700 then climbing left turn to 3000 direct ENE VOR/DME and hold.
--	-------------------	---

ATIS 119.05	PORTLAND APP CON ★ 119.75 269.35	PORTLAND TOWER ★ 120.9 0 (CTAF) 257.8	GND CON 121.9	UNICOM 122.95
-----------------------	--	---	-------------------------	-------------------------

