

ILS or LOC RWY 11
PORTLAND INTL JETPORT (PWM)

MISSED APPROACH: Climb to 600 then climbing right turn to 3000 direct ENE VOR/DME and hold.

NE-1, 03 SEP 2026 to 01 OCT 2026