

TACAN DHK Chan 36	APCH CRS 326°	Rwy Idg TDZE Arprt Elev N/A N/A 761	[USAF]		RANDOLPH AFB (KRND)	
RADAR required for missed approach monitoring			MISSED APPROACH: Track 327° to 1500, then climbing right turn heading 084° to 3000. Intercept DHK TACAN R-054 direct WIMVI and hold.			
* Circling not authorized SW of Rwy 15L-33R.						
ATIS ★ 290.525	SAN ANTONIO APP CON 128.05 318.1	TOWER ★ 128.25 294.7	GND CON 119.65 275.8	HANGOVER ATIS ★ 327.8	HANGOVER TOWER ★ 120.5 291.1	HANGOVER GND CON 124.75 353.75

