

WAAS

CH **82738**

W30A

APP CRS

308°

Rwy Ldg

4652

TDZE

2706

Apt Elev

2706

RNAV (GPS) RWY 30

HETTINGER/JB LINDQUIST RGNL (HEI)

⚠

For uncompensated Baro-VNAV systems, LNAV/VNAV NA below -20°C (-4°F) or above 54°C (130°F). DME/DME RNP-0.3 NA. Circling NA northeast of Rwy 12-30. Circling NA to Rwys 17 and 35.

MISSED APPROACH:

Climb to 6000 direct HAYNI and hold, continue climb-in-hold to 6000.

ASOS 119.925	MINNEAPOLIS CENTER 124.25 236.825	UNICOM 122.8 (CTAF) 1
------------------------	---	---------------------------------

ELEV 2706	TDZE 2706	6000 HAYNI VGSi and RNAV glidepath not coincident (VGSi Angle 3.00/TCH 25).			
*LNAV only		IBOXE 5 NM Holding Pattern			
*1.7 NM to RWY 30		KAKUH 4300			
RWY 30		IBOXE 5000			
1.7 NM		3.2 NM			
6 NM		GP 3.00° TCH 40			
CATEGORY	A	B	C	D	
LPV DA	2956-1		250 (300-1)		
LNAV/VNAV DA	3233-1 7/8		527 (600-1 7/8)		
LNAV MDA	3260-1	554 (600-1)	3260-1 5/8	554 (600-1 5/8)	
CIRCLING	3260-1	554 (600-1)	3260-1 5/8	3460-2 1/2	754 (800-2 1/2)

HETTINGER, NORTH DAKOTA

Amdt 1 26MAY16

46°01'N-102°39'W

HETTINGER/JB LINDQUIST RGNL (HEI)

RNAV (GPS) RWY 30