


ARRIVAL ROUTE DESCRIPTION

OKNIE TRANSITION (OKNIE.SUTHU2)
TOCOS TRANSITION (TOCOS.SUTHU2)

From SUTHU on track 153° to EGUYU.

LANDING RUNWAY 3L: From EGUYU on track 153° to cross SEATO at 6000 and at 210K, then on heading 213°. Expect RADAR vectors to final approach course.

LANDING RUNWAYS 21L/R: From EGUYU on track 153° to cross SEATO at 6000 and at 210K, then on heading 103°. Expect RADAR vectors to final approach course.

LOST COMMUNICATIONS: From SEATO, execute ILS or LOC RWY 21L or TACAN RWY 3L approach. If unable, hold at SEATO as depicted, maintain 6000.