


NOTE: Chart not to scale. NOTE: DME required.

ARRIVAL ROUTE DESCRIPTION

BLYTHE TRANSITION (BLH.CLOWD1): From over BLH VORTAC on BLH R-278 and PSP R-072 to CLOWD DME. Thence. . . .

DECAS TRANSITION (DECAS.CLOWD1): From over DECAS INT on BLH R-278 and PSP R-072 to CLOWD DME. Thence. . . .

GOFFS TRANSITION (GFS.CLOWD1): From over GFS VORTAC on GFS R-185 and TNP R-028 to TNP VORTAC, then on TNP R-199 to CLOWD DME. Thence. . . .

NEEDLES TRANSITION (EED.CLOWD1): From over EED VORTAC on EED R-216 and TRM R-037 to UBABE DME, then on PSP R-072 to CLOWD DME. Thence. . . .

. . . .From over CLOWD DME on TRM R-021 to TRM VORTAC. Expect RADAR vectors to final approach course.

SW-3, 26 NOV 2026 to 24 DEC 2026
SW-3, 26 NOV 2026 to 24 DEC 2026