AIRPORT CERTIFICATION INFORMATION BULLETIN



Eastern Region
Federal Aviation Administration
Airports Division, AEA-620
Safety & Standards Branch
1 Aviation Plaza,
Jamaica NY 11434

AEA-10-11
9/30/11

Bulletin: 2011-10
Subject: Snow and Ice Control Plan
Issue Date: September 29, 2011
Revised Date:

Prepared by: Evelyn Martinez & Frank Loprano
Phone: 718-553-3348/ 718-553-2543

Contact: Please contact your assigned Airport Certification Safety Inspector with further questions.

Application: This bulletin is being sent to Part 139 Airport Certificate holders to provide a sample Snow and Ice Control Plan Template (SICP) and review checklist.

Background: In support of the changes to AC 150/5200-30C, Airport Winter Safety and Operations, the FAA Eastern Region has provided a sample SICP for your airport to consider when revising your plan. While this format is not mandatory, we feel this template will assist your airport in better compliance with 14 CFR Part 139. Additionally, this format will ensure a more timely review and approval process for both FAA and your airport.

Action Required: As noted under page 1 of AC 150/5200-30C, Application, revised SICPs were required by April *30*, 2009 to address the AC changes. In addition, airports are required to conduct annual reviews (reference pg. 8, Para 2-2). During this review you may use both the SICP template and review checklist provided per this Bulletin to ensure your plan is up to date.

Please also review, Eastern Region Cert Bulletin 11-03, Best Practices for Winter Operations. http://www.faa.gov/airports/eastern/airport_safety/cert_bulletins/

Attachments: SICP Template, SICP Checklist