Close

```
QK ATLXRXA
.RWAXYYA 030427
GG KCFCZDZX KDOMYFYX KFSAYXYX KIADXCLX PANCYAYX KRWAYAYX
030427 KRWAXYYA
AAT-1    ATA-10    ATB-1    ATP-200   ATR-300   ATX-420
AAT-20   ATA-100   ATP-1    ATP-282   ATT-1     ATX-500
AAT-30   ATA-200   ATP-100  ATP-300   ATX-100   AEO-100
AAT-200  ATA-300   ATP-120  ATR-1     ATX-300   ATSC
ATA-1    ATA-400   ATP-130  ATR-100   ATX-400

KRWA NOUS2 030400
GENOT RWA 11/14
N8260.71
GG ALRGNS 1/200/600
AAS-100, AJV-3, AJV-E2, AJV-C2, AJV-W2
ALL AFS-400 (401/402/405/407/408/410/420/430/440/450/460/470)
XVM
////PART 1 OF 2////
EFFECTIVE: 04/25/2011
CANCELLATION: 04/24/2012
SUBJ: CHANGE TO FAA ORDER 8260.52, CHAPTER 1, TABLE 1-4.
THIS NOTICE PROVIDES UPDATED VALUES IN TABLE 1-4 IDENTIFIED IN
AFS-420 MEMORANDUM DATED FEBRUARY 14, 2006 "SAFETY CORRECTION
TO FAA ORDER 8260.52, UNITED STATES STANDARD FOR REQUIRED
NAVIGATION PERFORMANCE (RNP) APPROACH PROCEDURES WITH
SPECIAL AIRCRAFT AND AIRCREW AUTHORIZATION REQUIRED (SAAAR)."
AFS-420 MEMORANDUM FEBRUARY 14, 2006, IS CANCELED AND IS ALSO
APPLICABLE TO ALL AREA NAVIGATION (RNAV) PROCEDURES. PLEASE
AMEND TABLE 1-4 TO READ: GREATER THAN OR EQUAL TO 500 FT AGL:
////END PART 1///
```

Close

```
QK ATLXRXA
.RWAXYYA 030429
GG KCFCZDZX KDOMYFYX KFSAYXYX KIADXCLX PANCYAYX KRWAYAYX
030429 KRWAXYYA
KRWA NOUS2 030400
GENOT RWA 11/14
N8260.71
GG ALRGNS 1/200/600
AAS-100, AJV-3, AJV-E2, AJV-C2, AJV-W2
ALL AFS-400 (401/402/405/407/408/410/420/430/440/450/460/470)
XVM
////PART 2 OF 2////
1)FLY BY TURNS: EQUAL TO OR LESS THAN 25 DEGREE BANK
ANGLE FOR RNP GREATER THAN OR EQUAL TO 1.0#; EQUAL TO OR
LESS THAN 20 DEGREE BANK ANGLE FOR RNP LESS THAN 1.0#. 2)
RADIUS TO FIX TURNS: EQUAL TO OR LESS THAN 23 DEGREE BANK
ANGLE FOR RNP GREATER THAN OR EQUAL TO 1.0; EQUAL TO OR
LESS THAN 20 DEGREE BANK ANGLE FOR RNP LESS THAN 1.0. #
INDICATES TO USE THE SMALLER OF HALF THE TRACK CHANGE OR
ABOVE AS APPROPRIATE. NO FURTHER CHANGES TO TABLE.
QUESTIONS MAY BE DIRECTED TO RICK DUNHAM, FLIGHT
STANDARDS SERVICE, FLIGHT PROCEDURE STANDARDS BRANCH,
AFS-420, AT 405-954-4164.
JOHN M. ALLEN
DIRECTOR, FAA FLIGHT STANDARDS SERVICE (AFS-1)
////END PART 2////
```