



U.S. Department
of Transportation
**Federal Aviation
Administration**

Office of Airport Safety and Standards
Airport Engineering Division

800 Independence Ave., SW
Washington, DC 20591

MAY 22 2013

Dear Industry Representative:

Federal Aviation Administration (FAA) Draft Advisory Circular (AC) 150/5345-27E, FAA Specification for Wind Cone Assemblies, is being circulated to interested industry associations to obtain comments and recommendations of actions to be taken.

Please review this draft and submit comments as appropriate. Additionally, please provide justification for all comments about issues you may have with the draft and recommended modifications. We may revise the final document as a result of comments received and further review by the Office of Airport Safety and Standards.

This AC provides standards and specifications for wind cone assemblies to be used to provide wind information to pilots of aircraft. We request concurrence with the enclosure. We will consider comments received by June 26, 2013, for inclusion in the advisory circular.

Submit comments on the provided INDUSTRY REVIEW COMMENTS MATRIX which references the paragraph in the question with your recommended change.

Please email the completed MATRIX to Thomas Mai at Thomas.Mai@faa.gov.

The document may be obtained in Adobe Acrobat PDF format from the FAA Airport Internet site at http://www.faa.gov/airports/resources/draft_advisory_circulars/

Sincerely,

John R. Dermody, P.E.
Manager, Airport Engineering Division