

Errata Sheet for Advisory Circular 150/5340-30G, Design and Installation Details for Airport Visual Aids

Last Update: 9/28/2012

This errata sheet logs content and/or coding errors identified after the AC was signed on September 21, 2012. These errors have been corrected in the PDF version of the AC available on the FAA website.

#	Description of Correction	Location in Document	Rationale	Date Error Corrected
1	Removed reference to exception in paragraph 2.1.2b(2) from last line of "Application" paragraph.	Page i	Exception paragraph was deleted from AC so this reference must be deleted as well.	9/28/12