

Flight Procedures Cover Page	Task Action: FLIGHT CHECK	Task Type: IAP	Estimated Chart Date: 09/03/2026	APWS Task ID: 0970F4891B7F4BD6A8E99AC59768A18F	APWS Project ID: E29FB7B08FCC4F0EB40A84F150DEB1A6
Procedure: RNAV (GPS) RWY 9 AMDT 2		Enroute: NO	Specialist: Kenney, Taylor		Agreement Number:
Airport ID: KSLK			Airport City: SARANAC LAKE		State: NY
Facility ID:	Facility Type:	Flight Inspection Remark Type: New FC Slot			
Procedure Comments: PENDING AIRNAV DATA USED CANCELS NOTAM FDC 4/2207 KSLK_RNAV_(GPS)_RWY_09_AMDT_2_1 = LP MISSED PENETRATION KSLK_RNAV_(GPS)_RWY_09_AMDT_2_2 = FULL PROCEDURE CRC REMAINDER CHANGED FROM E9557D90 TO 4D9592BE POC: ROB HAMILTON, AJV-A433, (405) 954-4608 8260-2 SMAIR 07/08/2026: THIS IS A CORRECTED COPY OF THE FORM APPROVED ON 07/06/2026. REQUIRED CHARTING: REMOVED IAP. QUALITY 16 CHECKED QUALITY 29 CHECKED QUALITY 40 CHECKED					

WAAS CH 93626 W09A	APP CRS 093°	Rwy Ldg TDZE 1644 Apt Elev 1663
--	------------------------	---



EXISTING

RNAV (GPS) RWY 9
ADIRONDACK RGNL (SLK)

RNP APCH-GPS.
Rwy 9 helicopter visibility reduction below 1 SM NA.
Straight-in Rwy 9 NA at night, Circling Rwy 5, 9, 27 NA at night.
-32°C

MISSED APPROACH: Climbing left turn to 6000 direct MUNZA and hold, continue climb-in-hold to 6000.

ASOS 124.175	BOSTON CENTER 120.35 342.25	UNICOM 123.0 (CTAF) 0
------------------------	---------------------------------------	---------------------------------



CATEGORY	A	B	C	D
LP MDA	2180-1	536 (600-1)	2180-1½	536 (600-1½)
LNVA MDA	2380-1	736 (800-1)	2380-2	736 (800-2)
CIRCLING	2500-1¼ 837 (900-1¼)	2660-1½ 997 (1000-1½)	2660-3 997 (1000-3)	2680-3 1017 (1100-3)

ELEV 1663 **D** TDZE 1644

