

Flight Procedures Cover Page	Task Action: Cancellation	Task Type: IAP	Estimated Chart Date: 10/31/2024	APWS Task ID: 11BE2FA29BD241AF984F204E56E64FBC	APWS Project ID: E16E91373DAF46CF8EC7A6AF118C1BC3
Procedure: HI-ILS OR LOC RWY 15 AMDT 1A		Enroute: NO	Specialist: Sarmiento, April		Agreement Number:
Airport ID: KBTV			Airport City: BURLINGTON		State: VT
Facility ID: BTV	Facility Type: ILS	Flight Inspection Remark Type:			
Procedure Comments: CANCEL PROCEDURE CONTACT CASIMIR TABAKA (405) 954-7931 Digitally signed by JOSEPH L ZEDER Sep 06, 2024 QUALITY 35 CHECKED					

HI-ILS or LOC RWY 15

LOC/DME I-BTV 110.3 Chan 40	APCH CRS 146°	Rwy Idg 7820 TDZE 326 Arpt Elev 335
---	-------------------------	--

CURRENT

TRICK LEAHY BURLINGTON INTL (KBTW)

TACAN required

MALSR

MISSED APPROACH: Climb to 1000, then climbing right turn to 8000 on BJA TACAN R-325 to ZIDOX/BJA 20.1 DME and hold. continue climb-in-hold to 8000.

* When ALS inop, increase CAT CDE RVR to 55, vis to 1 mile.



ATIS
123.8 269.9



APP CON
121.1 278.8

TOWER ★
118.3 (CTAF) **L**257.8

GND CON
126.3 348.6

CLNC DEL
119.15


NOT FOR CIVIL USE




LOCALIZER 110.3
I-BTV 
Chan 40

EMERG SAFE ALT 100 NM 8500

Use I-BTV DME
when on localizer course.



ELEV 335	D	TDZE 326
		Rwy 1 ldg 3886'
		Rwy 19 ldg 3386'
		Rwy 15 ldg 7820'
		Rwy 33 lda 7819'



CATEGORY	C	D	E
S-ILS 15	576/40	250	(300-34)
S-LOC 15 *	700/40	374	(400-34)
C CIRCLING	1220-234 885 (900-234)	1380-3 1045 (1100-3)	1500-3 1165 (1200-3)

MIRL Rwy 1-19 **L**
HIRL Rwy 15-33 **L**