

Flight Procedures Cover Page	Task Action: P-NOTAM	Task Type: IAP	Estimated Chart Date: 09/03/2026	APWS Task ID: 1487DF3189EA4357B35FA172C466A1DE	APWS Project ID: 24AA00CD903F4AA8A32DA00061B1B5DB
Procedure: VOR RWY 17 AMDT 1C		Enroute: NO	Specialist: Johnson, Timothy		Agreement Number:
Airport ID: KRBD			Airport City: DALLAS		State: TX
Facility ID: CVE	Facility Type: VOR_DME	Flight Inspection Remark Type:			
Procedure Comments: Visibility Initiative (Garmin) - Update IAP visibility minimums IAW Order 8260.3, Chapter 3, Section 3-3. Visibility Minimums. PROCESSED IAW TECHNICAL SUPPORT GROUP (AJF-17) MEMO DATED 07/07/2021, SUBJECT: GUIDANCE FOR PROCEDURAL CHANGES REQUIRING FLIGHT INSPECTION/VALIDATION. CONTACT: CASEY HILL (405) 954-0624. QUALITY 6 SN 4/15/26 CHECKED QUALITY 9 CHECKED BEGUE					

VOR/DME CVE	APP CRS	Rwy Ldg	3800
116.2	165°	TDZE	658
Chan 109		Apt Elev	661

VOR RWY 17
DALLAS EXEC (RBD)

DME required. RADAR required for procedure entry.	MISSED APPROACH: Climb to 3000 on CVE VOR/DME R-165 to MOLES/22 DME and hold.
Rwy 17 helicopter visibility reduction below 3/4 SM NA.	

ATIS 126.35	LONE STAR APP CON 125.2 343.65	EXECUTIVE TOWER ★ 127.25 (CTAF) 0	GND CON 119.475	UNICOM 122.95
----------------	-----------------------------------	--------------------------------------	--------------------	------------------

