

Flight Procedures Cover Page	Task Action: Amendment	Task Type: FIX	Estimated Chart Date: 10/05/2023	APWS Task ID: 1C02DD2EDEEF4B26A98FD9CE2F71230F	APWS Project ID: E4DF56886EB146F887CE74D90CA5A3B9
Procedure: FIX LEEAH 20 NJ US		Enroute: YES	Specialist: Campbell, Colin		Agreement Number:
Airport ID:			Airport City:		State:
Facility ID:	Facility Type:	Flight Inspection Remark Type:			
<div>Procedure Comments:</div> <div>MULTIPLE FIXES: LEEAH REV 20, TUBER REV 13</div> <div>ADDED "V229" BACK TO FIX USE</div> <div>CONTACT: JASON KRETSCHMER, AJV-A421, (405) 954-4019</div> <div>PROCESSED IAW TECHNICAL SUPPORT GROUP (AJF-17) MEMO DATED 07/07/2021, SUBJECT: GUIDANCE FOR PROCEDURAL CHANGES REQUIRING FLIGHT INSPECTION VALIDATION.</div> <div>07/12/2023</div> <div>QUALITY 14 CHECKED</div>					