

Flight Procedures Cover Page	Task Action: Amendment	Task Type: FIX	Estimated Chart Date: 08/07/2025	APWS Task ID: 1CCB266342D649FD9F8E7C6308D08923	APWS Project ID: C62C0E548AA34F24BC7D881DDC877336
Procedure: FIX IMPOR 2 WA US		Enroute: NO	Specialist: Bruce, Richard		Agreement Number:
Airport ID:			Airport City:		State:
Facility ID:	Facility Type:	Flight Inspection Remark Type:			
Procedure Comments: VICTORIA (YYJ) VOR/DME CONVERSION TO STAND-ALONE DME. MULTIPLE FIXES (2): FIX BUICK REV 4 CA (CANADA). FIX IMPOR REV 2 WA US. CONTACT RAKE MCGRAW, AJV-A422, (405) 954-8711.					

QUALITY
29
CHECKED