

Flight Procedures Cover Page	Task Action: FLIGHT CHECK	Task Type: IAP	Estimated Chart Date: 03/19/2026	APWS Task ID: 1EFE64DF1E7641648511E0F984CCD96F	APWS Project ID: 2C3BEF9B12CD4BE3861FC640A194ADFA
Procedure: RNAV (GPS) RWY 18 AMDT 0B		Enroute: NO	Specialist: Dumar, Ralph		Agreement Number:
Airport ID: 61A			Airport City: CAMDEN		State: AL
Facility ID:	Facility Type:	Flight Inspection Remark Type: New FC Slot			

Procedure Comments:
 ABBREVIATED AMENDMENT
 PROCESSED IAW TECHNICAL SUPPORT GROUP (AJF-17) MEMO DATED 07/07/2021 GUIDANCE FOR PROCEDURAL CHANGES REQUIRING FLIGHT INSPECTION/VALIDATION

AIRPORT ACTIVE DATA USED.

REMARKS: PROJECT TO CLEAR FDC NOTAM 5/3461
 CONTACT RAKE MCGRAW (AJV-A422)- 405-954-8711

QUALITY
9
CHECKED
BEGUE

QUALITY
13
CHECKED

APP CRS	Rwy Idg	4303
182°	TDZE	143
	Apt Elev	143



RNAV (GPS) RWY 18

CAMDEN MUNI (61A)

RNP APCH - GPS.





- Procedure NA at night. Helicopter visibility reduction below 1 SM NA.
- NA Use SEM altimeter setting; when not received, use A08 altimeter setting and increase all MDAs 20 feet.

MISSED APPROACH: Climb to 3500 direct JOLUM and hold, continue climb-in-hold to 3500.

SEM AWOS-3PT
119.15

ATLANTA CENTER
120.55 270.25

CTAF
122.9



CATEGORY	A	B	C	D
LNVA MDA	760-1	617 (700-1)	760-1¾	617 (700-1¾)
CIRCLING	760-1 617 (700-1)	780-1 637 (700-1)	900-2¼ 757 (800-2¼)	1060-3 917 (1000-3)

MIRL Rwy 18-36

SE-4, 02 OCT 2025 to 30 OCT 2025

SE-4, 02 OCT 2025 to 30 OCT 2025