


Flight Procedures Cover Page	Task Action: FLIGHT CHECK	Task Type: IAP	Estimated Chart Date: 10/02/2025	APWS Task ID: 2AABEC44C77B4A95B28697221A49B3FA	APWS Project ID: 4A8B836C90834922BA64FC3817AA43B9
Procedure: VOR RWY 5 AMDT 5		Enroute: NO	Specialist: Pipkin, Ryan		Agreement Number:
Airport ID: KEDN			Airport City: ENTERPRISE		State: AL
Facility ID: EDN	Facility Type: VOR	Flight Inspection Remark Type: New FC Slot			
Procedure Comments: DEVELOPED USING ACTIVE AIRNAV AIRPORT AND RUNWAY DATA FOR KEDN. BVG NDB DECOMMISSIONING. CONTACT RAKE MCGRAW (AJV-A422)- 405-954-8711 QUALITY 41 CHECKED QUALITY 34 CHECKED					

VOR RWY 5
ENTERPRISE MUNI (EDN)



MISSED APPROACH: Climbing left turn to 2500 in EDN VOR holding pattern, continue climb-in-hold to 2500.

T Circling Rwy 23 NA at night. When local altimeter setting not received, use OZR altimeter setting and increase all MDAs 40 feet.

CAIRNS APP CON ★
133.45 239.275

UNICOM
122.8 (CTAF) **L**

PROTOTYPE-NOT FOR NAVIGATION



VOR EDN 116.6	APP CRS 065°	Rwy Idg 5080 TDZE 360 Apt Elev 361
-------------------------	------------------------	--

VOR RWY 5

ENTERPRISE MUNI(EDN)

▼ ▲ NA ADF or RADAR required. Use Cairns AAF (Fort Novosel) altimeter setting.	MISSED APPROACH: Climbing left turn to 2500 in EDN VOR holding pattern.
---	---

AWOS-3PT 118.9	CAIRNS APP CON ★ 133.45 239.275	UNICOM 122.8 (CTAF) 0
--------------------------	---	---------------------------------

