

IAP	RNAV (RNP) Z RWY 34L	4	KDEN	DENVER	CO (US)
IAP	RNAV (GPS) RWY 33		KFNL	FORT COLLINS/LOVELAND	CO (US)
STAR	TOMSN	1, 2	KBKF	AURORA	CO (US)
STAR	TOMSN	1, 2	KAPA	DENVER	CO (US)
STAR	TOMSN	1, 2	KBJC	DENVER	CO (US)
STAR	TOMSN	1, 2	KCFO	DENVER	CO (US)
STAR	TOMSN	1, 2	KDEN	DENVER	CO (US)
STAR	TOMSN	1, 2	KFNL	FORT COLLINS/LOVELAND	CO (US)
STAR	TOMSN	1, 2	KGXY	GREELEY	CO (US)

REQUIRED CHARTING: SECTIONAL, STAR, IAP, EN ROUTE LOW, CONTROLLER LOW

COMPULSORY REPORTING POINT: NO

RECORD REVISION NUMBER: 15 **DATE OF REVISION:** 11/27/2025

REASON FOR REVISION:

CONTROLLING OBSTRUCTION UPDATED PAT 4 AND PAT 5
 PRECIPITOUS TERRAIN ADDITIONS UPDATED PAT 4
 REMARKS UPDATED PAT 4 AND PAT 5 CONTROLLING OBSTRUCTION FROM 8510.74 TO 8530.08 FROM 7938 EQUIV TO 7941 EQUIV.
 FIX USE REMOVED ILS OR LOC RWY 34R, ILS RWY 34R (CAT II/CAT III), ILS RWY 34R (SA CAT I), RNAV (GPS) Y RWY 34R, RNAV (RNP) Z RWY 34R @ KDEN REMOVED PAT 6 FROM ILS OR LOC RWY 34L
 FIX USE ADDED RNAV (GPS) Y RWY 34L @ KDEN

INITIATED BY: **DATE:** **ORGANIZATION:** **NAME:**

OFFICE OF PRIMARY RESPONSIBILITY: AJV-A433 **NAME:** JOSHUA DUGAN

APPROVED BY: **DATE:** 10/23/2025 **OFFICE:** AJV-A433 **NAME:** ROBERT HAMILTON

SIGNATURE:

