


Flight Procedures Cover Page	Task Action: FLIGHT CHECK	Task Type: IAP	Estimated Chart Date: 05/14/2026	APWS Task ID: 40440AA6FE6A427FB71499E00B985AED	APWS Project ID: 5645807BD3324774950EA2DBE055F31B
Procedure: VOR RWY 21 AMDT 7		Enroute: NO	Specialist: Gorman, Barbara		Agreement Number:
Airport ID: KTCC			Airport City: TUCUMCARI		State: NM
Facility ID: TCC	Facility Type: VORTAC	Flight Inspection Remark Type: New FC Slot			
Procedure Comments: ACTIVE DATA USED FOR AIRPORT AND RUNWAY. REMOVE NOTAM FDC 4/4153. KTCC_VOR_RWY_21_AMDT_7_1 INCLUDES LNAV TRAP SHOWING THE PRIMARY MA PENETRATOR. KTCC_VOR_RWY_21_AMDT_7_2 IS FINAL TRAP WITH CONTROLLING OBSTACLES. CONTACT: CASIMIR TABAKA 405.954.7931 PROCESSED IAW TECHNICAL SUPPORT GROUP (AJF-17) MEMO DATED 07/07/2021, SUBJECT: GUIDANCE FOR PROCEDURAL CHANGES REQUIRING FLIGHT INSPECTION/VALIDATION. QUALITY 20 CHECKED QUALITY 9 CHECKED BEGUE					

VORTAC TCC 113.6 Chan 83	APP CRS 201°	Rwy Ldg TDZE 4047 Apt Elev 4065
--	------------------------	---


VOR RWY 21
TUCUMCARI MUNI (TCC)

▼ If local altimeter setting not received, procedure NA. Circling NA for Cat D north of Rwy 8 and northwest of Rwy 21.	MISSED APPROACH: Climb to 5100 then climbing left turn to 6100 direct TCC VORTAC and hold.
--	--

ASOS 119.275	ALBUQUERQUE CENTER 126.85 285.6	UNICOM 122.95 (CTAF) 0
------------------------	---	----------------------------------



ELEV 4065	TDZE 4047
-----------	-----------



MIRL Rwy 3-21 and 8-26 0