

Flight Procedures Cover Page	Task Action: Amendment	Task Type: FIX	Estimated Chart Date: 06/12/2025	APWS Task ID: 53637D2EA16243FABAC5C0DEA20CA981	APWS Project ID: 87CF950CC00A44809CDE92A004CAF066
Procedure: FIX BNTLY 2 VA US		Enroute: YES	Specialist: Smart, Phillip		Agreement Number:
Airport ID:			Airport City:		State:
Facility ID:	Facility Type:	Flight Inspection Remark Type:			
<div>Procedure Comments:</div> <div>Multiple Fixes: BNTLY, DEWET, WILIZ</div> <div>Processed IAW Technical Support Group (AJF-17) Memo dated 07/07/2021 Guidance for Procedural Changes Requiring Flight Inspection/Validation.</div> <div>CONTACT ROBERT HAMILTON 405-954-4608. FEDERAL AVIATION ADMINISTRATION.</div> <div>8260-2 WILIZ</div> <div>04/04/2025: THIS IS A CORRECTED COPY OF THE FORM APPROVED ON 03/21/2025.</div> <div>FIX USE: ADDED PAT 2 TO KPSK RNAV (GPS) RWY 6.</div> <div>QUALITY 16 CHECKED</div> <div>QUALITY 40 CHECKED</div>					