

Flight Procedures Cover Page	Task Action: Amendment	Task Type: FIX	Estimated Chart Date: 05/15/2025	APWS Task ID: 574E603C499E4EF695249A3AFDB26D4C	APWS Project ID: AB3201D4EA0D44969DA458AAC7C84E25
Procedure: FIX BURMA 5 AK US		Enroute: NO	Specialist: Patterson, Lawrence		Agreement Number:
Airport ID:			Airport City:		State:
Facility ID:	Facility Type:	Flight Inspection Remark Type:			
<div>Procedure Comments: 8260-2 REVISIONS FOR THIRD PARTY SPECIAL. BURMA, AK REV 5, DIFER, AK REV 4, HEXAX, AK REV 3. PROCESSED IAW TECHNICAL SUPPORT GROUP (AJF-17) MEMO DATED 07/07/2021, SUBJECT: GUIDANCE FOR PROCEDURAL CHANGES REQUIRING FLIGHT INSPECTION/VALIDATION. CONTACT: DON LANIER, AJV-A441 MANAGER, 405 954 8242 04/1/2025: THIS IS A CORRECTED COPY OF THE FORM APPROVED ON 03/18/25. 1. ADDED CONTROLLER LOW TO REQUIRED CHARTING DIFER 8260-2.</div> <div>QUALITY 18 CHECKED</div>					