

[Print](#)

Project Name: BWD

Project Reason: KBWD LOC RWY 17 incorrect radial R-356 should read R-352 within missed app instructions per flight inspection OP-06-077-24 (03/15/2025). KBWD VOR RWY 17 incorrect aircraft category (Cat A should read Cat C) within inoperative ALS instructions.

Last Updated By: PHILLIP SMART

Last Updated At: 2025-03-17 15:33:15.47532

Status: Verified
5/6866

Digitally signed by
ROBERT G HAMILTON
Mar 24, 2025



!FDC X/XXXX BWD IAP BROWNWOOD RGNL, BROWNWOOD, TX. VOR RWY 17 ORIG ... CHANGE INOPERATIVE ALS NOTE TO READ: FOR INOPERATIVE ALS, INCREASE S-17 CAT C AND D VISIBILITY TO 1 7/8 SM THIS IS VOR RWY 17 ORIG-A. 2503171533-PERM