Flight Procedures Cover Page	Task Action: FLIGHT CHECK	Task Type: IAP	Estimated Chart Date: 06/12/2025	APWS Task ID: 63449B19F23845F9BC8800F96505083B	APWS Project ID: 64ECA26FC3EA42F785F9456B5164B37D	
Procedure: COPTER RNAV (GPS) M 350 ORIG		Enroute: NO	Specialist: Hirst, Charles		Agreement Number:	
Airport ID: ME50			Airport City: MILLINOCKET		State: ME	
Facility ID:	, ,,	Flight Inspection Remar New FC Slot	ight Inspection Remark Type: ew FC Slot			

Procedure Comments:

SPECIAL IAP.

Develop IAP for ME50, MILLENOCKET, ME; for Helicopter Air Ambulance use only to allow for direct access to and from low-level ZK411 to the southeast. The helipad is far enough from the 14 CFR Part 97 approach that VFR weather minimums are required to transition from the MAP.

For additional questions contact Robert Hamilton, Manager 405-954-4608

awaiting FIG. do not send to FC until incorporated into this S file.

OUALITY 38

QUALITY





