

Flight Procedures Cover Page	Task Action: FLIGHT CHECK	Task Type: FIX	Estimated Chart Date: 11/30/2023	APWS Task ID: 6F1C41D372FD4CB8A1E52D7FCEC04BB9	APWS Project ID: 28B3E2CE065A438286754634C4A12D9A
Procedure: FIX MOIST 4 WY US		Enroute: YES	Specialist: Ownbey, Steve		Agreement Number:
Airport ID:			Airport City:		State:
Facility ID:	Facility Type:	Flight Inspection Remark Type: New FC Slot			
<div>Procedure Comments:</div> <div>REQUEST TABLE TOP - FIX WAS ALREADY ESTABLISHED, UPDATING 8260-2 TO REFLECT CURRENT OPERATIONS.</div> <div>ESV(s): MEDICINE (BOW) VDME (1) FIX MOIST MULLAN PASS (MLP) VDME (1) FIX TWIGY</div> <div>BOTH OF THESE ESV's ARE GRANDFATHERED</div> <div>CONTACT DAVE DANNER: AJV-A442, 405-954-5077</div> <div><div>QUALITY 32 CHECKED</div><div>Digitally signed by PABLO ORTIZ-JR May 17, 2023</div></div>					

ESV Details

Originating Office :AJV-5433		Airspace Docket Number :		Request Type :Establish		
Facility Data						
Chart Name:MEDICINE BOW MBW		City:MEDICINE BOW		Ident:MBW		State:WY
Type/Class: H-VOR		Frequency: M116.85		Reference Number: 23032236		
Extended Service Volume Data: (Requesting Officer)						
ESV ID	Radial 1	Radial 2	Distance	Minimum Altitude	Maximum Altitude	
FAA 200322 - 008	92		42	75	120	
Requirement: GRANDFATHERED: CURRENT ESTABLISHED FIX MOIST USED V6-132						
Signature:Ownbey Steve		Routing Symbol:AJV-A442				Date:03/28/2023
Extended Service Volume Data: (FIFO)						
ESV ID	Radial 1	Radial 2	Distance	Minimum Altitude	Maximum Altitude	Action Type
FAA 200322 - 008	92					
Requirement/Remarks:						
Signature:		Routing Symbol:			Date:	