


Flight Procedures Cover Page	Task Action: Cancellation	Task Type: IAP	Estimated Chart Date: 06/12/2025	APWS Task ID: 70430ADB135249DD89A2D0D213B7C459	APWS Project ID: 49E47FA87B584AF7B34CAC9C44C7898B
Procedure: VOR/DME OR GPS RWY 7 AMDT 5A		Enroute: NO	Specialist: Tyler, George		Agreement Number:
Airport ID: KDLC			Airport City: DILLON		State: SC
Facility ID:	Facility Type:	Flight Inspection Remark Type:			
Procedure Comments: IAP CANCELLED PER THE FLO VOR MON PROGRAM. CANCELS NOTAMs FDC 3/9692 AND FDC 4/4089. CONTACT DAVID DANNER, AJV-A421, 405-954-5077. QUALITY 35 CHECKED					

VORTAC FLO	APP CRS	Rwy Idg	3000
115.2	051°	TDZE	134
Chan 99		Apt Elev	134

OLD

VOR/DME or GPS RWY 7
DILLON COUNTY (DLC)

▼ ▲NA Use Florence altimeter setting.	MISSED APPROACH: Climbing left turn to 2000 via FLO R-051 to DEMIC 14 DME and hold.
FLORENCE APP CON ★ 118.6 341.7	CTAF 122.9



(CFBXX) FLO 7 2000			DEMIC FLO 14 1700	2000 FLO R-051	DEMIC FLO 14
Procedure Turn NA			051°	RW07 FLO 19.1	
7 NM			5.1 NM		
CATEGORY	A	B	C	D	
S-7	660-1	526 (600-1)	660-1½ 526 (600-1½)	NA	
CIRCLING	700-1	566 (600-1)	700-1½ 566 (600-1½)	NA	

