

Flight Procedures Cover Page	Task Action: P-NOTAM	Task Type: IAP	Estimated Chart Date: 10/29/2026	APWS Task ID: 7A886842DC1C4F31971215894082E4BD	APWS Project ID: 1B00DAFC2DB24F4385ACE045CD45B9F3
Procedure: RNAV (GPS) RWY 18 ORIG-D		Enroute: NO	Specialist: Johnson, Timothy		Agreement Number:
Airport ID: KTAZ			Airport City: TAYLORVILLE		State: IL
Facility ID:	Facility Type:	Flight Inspection Remark Type:			
Procedure Comments: Visibility Initiative (Garmin) - Update IAP visibility minimums IAW Order 8260.3, Chapter 3, Section 3-3. Visibility Minimums. PROCESSED IAW TECHNICAL SUPPORT GROUP (AJF-17) MEMO DATED 07/07/2021, SUBJECT: GUIDANCE FOR PROCEDURAL CHANGES REQUIRING FLIGHT INSPECTION/VALIDATION. CONTACT: CASEY HILL (405) 954-0624. QUALITY 6 SN 4/22/26 CHECKED QUALITY 29 CHECKED					

APP CRS	Rwy Ldg	4001
179°	TDZE	620
	Apt Elev	622

RNAV (GPS) RWY 18
TAYLORVILLE MUNI (T.A.Z.)

▼ DME/DME RNP-0.3 NA. Visibility reduction by helicopters NA. When local altimeter setting not received, use Springfield altimeter setting and increase all MDA 80 feet, increase LNAV and Circling Cat C visibility ¼ SM. ▲	MISSED APPROACH: Climb to 2500 direct DAYRE and hold.
--	--

AWOS-3PT 123.875	SAINT LOUIS APP CON 126.15 323.0	UNICOM 122.8 (CTAF) 0
---------------------	-------------------------------------	---------------------------------

