

Flight Procedures Cover Page	Task Action: P-NOTAM	Task Type: IAP	Estimated Chart Date: 10/29/2026	APWS Task ID: 7D0A8C462C4F40FDB380E17F9716632E	APWS Project ID: 9473760089C94E249BEBF9EFB26491BA
Procedure: RNAV (GPS) RWY 10 AMDT 2A		Enroute: NO	Specialist: Johnson, Timothy		Agreement Number:
Airport ID: PAAQ			Airport City: PALMER		State: AK
Facility ID:	Facility Type:	Flight Inspection Remark Type:			
Procedure Comments: Visibility Initiative (Garmin) - Update IAP visibility minimums IAW Order 8260.3, Chapter 3, Section 3-3. Visibility Minimums. PROCESSED IAW TECHNICAL SUPPORT GROUP (AJF-17) MEMO DATED 07/07/2021, SUBJECT: GUIDANCE FOR PROCEDURAL CHANGES REQUIRING FLIGHT INSPECTION/VALIDATION. CONTACT: CASEY HILL (405) 954-0624. QUALITY 6 SN 4/27/26 CHECKED					

WAAS CH 40425 W10A	APP CRS 097°	Rwy Ldg TDZE Apt Elev	3616 233 249
--	------------------------	-----------------------------	---

RNAV (GPS) RWY 10

WARREN "BUD" WOODS PALMER MUNI (PAQ) (PAAQ)

RNP APCH.


▼

▲

Circling NA northeast of Rwy 16-28. Procedure NA at night.
Rwy 10 helicopter visibility reduction below 1 SM NA.

MISSED APPROACH: (Do not exceed 185K until INICE)
Climbing right turn to 3600 direct INICE and hold.

AFIS 134.75	ANCHORAGE APP CON 118.6 290.5	PALMER RADIO 123.6 (CTAF) 0 122.4
-----------------------	---	---



LEYIT					INICE				
3300					3600				
067°					097°				
2300					1300				
6.1 NM					3.2 NM				
CATEGORY					RWY 10				
LP MDA					3.2 NM to RWY 10				
LNNAV MDA					3.2 NM				
CIRCLING					3.2 NM				
760-1 527 (600-1)					760-1½ 527 (600-1½)				
820-1 587 (600-1)					820-1⅝ 587 (600-1⅝)				
860-1 611 (700-1)					1300-3 1051 (1100-3)				
940-1 691 (700-1)									

