

Flight Procedures Cover Page	Task Action: P-NOTAM	Task Type: IAP	Estimated Chart Date: 10/02/2025	APWS Task ID: 7EB5DF8292DD4950932AD54FB0108CC0	APWS Project ID: F02CAECB85AC463C8F3316F6919FCBD3
Procedure: RNAV (GPS) RWY 5 AMDT 1C		Enroute: NO	Specialist: Armentrout, Britney		Agreement Number:
Airport ID: KEDN			Airport City: ENTERPRISE		State: AL
Facility ID:	Facility Type:	Flight Inspection Remark Type:			
Procedure Comments: PROCESSED IAW TECHNICAL SUPPORT GROUP (AJF-17) MEMO DATED 07/07/2021 GUIDANCE FOR PROCEDURAL CHANGES REQUIRING FLIGHT INSPECTION/VALIDATION. CIRCLING RWY 23 NA AT NIGHT. CONTACT RAKE MCGRAW AJV-A422 405-954-8711. QUALITY 21 CHECKED					

OLD

ENTERPRISE, ALABAMA

AL-6568 (FAA)

23278


WAAS CH 72614 W05A	APP CRS 055°	Rwy Idg 5080 TDZE 360 Apt Elev 361
--	------------------------	---

RNAV (GPS) RWY 5

ENTERPRISE MUNI (EDN)

T Baro-VNAV NA. For uncompensated Baro-VNAV systems, LNAV/VNAV NA below -15°C (5°F) or above 54°C (130°F). DME/DME RNP-0.3 NA.
A NA Use Cairns AAF (Fort Novosel) altimeter setting.

MISSED APPROACH: Climb to 2500 direct CEYLU and left turn via track 295° to HAXES and left turn via track 191° to ROTOY and hold.



SE-4, 23 JAN 2025 to 20 FEB 2025

SE-4, 23 JAN 2025 to 20 FEB 2025

ENTERPRISE, ALABAMA
Amdt 1B 30DEC21

31°18'N-85°54'W

ENTERPRISE MUNI (EDN)

RNAV (GPS) RWY 5