

Flight Procedures Cover Page	Task Action: FLIGHT CHECK	Task Type: IAP	Estimated Chart Date: 09/03/2026	APWS Task ID: 7F730C782C49414D8AE13BB731804E15	APWS Project ID: 3366B48AACC04BC9BE91D6483583DCA6
Procedure: RNAV (GPS) RWY 5 AMDT 0D		Enroute: NO	Specialist: Taylor, Jantzen		Agreement Number:
Airport ID: KCAK			Airport City: AKRON		State: OH
Facility ID:	Facility Type:	Flight Inspection Remark Type: New FC Slot			
Procedure Comments: CLEARS NOTAM !FDC 5/6540 ACTIVE DATA USED FOR AIRPORT, NAVAIDS AND RUNWAY. CONTACT RAKE MCGRAW, AJV-A422, 405.954.8711 QUALITY 23 CHECKED QUALITY 39 CHECKED					

AKRON, OHIO

AL-638 (FAA)

25051

WAAS CH 77620 W05A	APP CRS 054°	Rwy Idg TDZE Apt Elev	8204 1199 1226
--	------------------------	-----------------------------	---

OLD

RNAV (GPS) RWY 5

AKRON-CANTON RGNL (CAK)



For uncompensated Baro-VNAV systems, LNAV/VNAV NA below -17°C (2°F) or above 46°C (114°F). DME/DME RNP-0.3 NA.
** RVR 1800 authorized with use of FD or AP or HUD to DA.

MALSR



MISSED APPROACH: Climb to 3000 direct EGGII and on track 048° to ACO VOR/DME and hold.

ATIS 121.05	CLEVELAND APP CON ★ 125.5 269.25	AKRON-CANTON TOWER 134.75 279.575	GND CON 121.7 348.6	CLNC DEL 132.05
-----------------------	--	---	-------------------------------	---------------------------

MISSED APCH FIX

4 NM

2048 Δ

EGGII

 Δ 1427 Δ 1699 Δ 2048

RW05

1330 Δ Δ 1279±(FAF)
CICEE3000
054°
(6)(IF/IAF)
JUNEX

4 NM

234°

054°

Procedure NA for arrival on
BSV VOR/DME airway radials
246 CW 322.

3000
289°
(9.8)BRIGGS
BSV

MSA RW05 25 NM

3100

ELEV 1226

D

TDZE 1199

4 NM
Holding Pattern

JUNEX

CICEE

3000

3000

EGGII

tr
048°

ACO

* LNAV only

*1.3 NM to RW05

RW05

3000

GP 3.00°
TCH 50

054°

234°

054°

054°

054°

054°

054°

054°

054°

054°

054°

054°

054°

054°

054°

054°

054°

AKRON, OHIO

Orig-C 12AUG21

40°55'N - 81°27'W

AKRON-CANTON RGNL (CAK)

RNAV (GPS) RWY 5

EC-2, 19 FEB 2026 to 19 MAR 2026

EC-2, 19 FEB 2026 to 19 MAR 2026