

Flight Procedures Cover Page	Task Action: FLIGHT CHECK	Task Type: FIX	Estimated Chart Date: 11/30/2023	APWS Task ID: 80EC20751DBB45C9AA194CFE1C588AEE	APWS Project ID: 2D0B5CE21FBF4B5889DDE39A0F7A6D9C
Procedure: FIX EXALT 10 MA US		Enroute: NO	Specialist: Martinelli, Tara		Agreement Number:
Airport ID:			Airport City:		State:
Facility ID:	Facility Type:	Flight Inspection Remark Type: New FC Slot			
<div>Procedure Comments: FILE NAME: MA_EXALT_ENR_11-30-23. ESV: (2) CONCORD (CON) VOR/DME CONTACT DAVE DANNER: AJV-A442, 405-954-5077. 8/16/2023: UPDATED COPY OF THE FORM DEVELOPED ON 7/10/2023. 8260-2 EXALT: 1. CHANGED FAC ENE AND CON MRA FROM 2500 TO 5000. 2. CHANGED ENE AND CON ESV MIN AT FROM 2500 TO 5000. 3. CHANGED PAT 1 MIN HOLDING FROM 2500 TO 5000 AND CHANGED MIN TEMP FROM 6 TO 7.</div> <div><div>QUALITY 32 CHECKED</div><div>Digitally signed by PABLO ORTIZ-JR Aug 30, 2023</div></div>					