

Flight Procedures Cover Page	Task Action: FLIGHT CHECK	Task Type: IAP	Estimated Chart Date: 05/16/2024	APWS Task ID: 8CA4E257BBFA4889809FBE3A521E8D34	APWS Project ID: CFC1DE67CAAB483C9E02DEF3C3CEE12A
Procedure: RNAV (GPS) RWY 23R AMDT 0E		Enroute: NO	Specialist: Milligan, Walker		Agreement Number:
Airport ID: KLCK			Airport City: COLUMBUS		State: OH
Facility ID:	Facility Type:	Flight Inspection Remark Type: New FC Slot			
Procedure Comments: ACTIVE DATA USED FOR LCK AIRPORT AND RUNWAYS YRK VOR MON FAS DATA CHANGED - CRC REMAINDER CHANGED DUE TO NEW LTP LOCATION IN AIRPORT SURVEY DATED 4/26/2022. CONTACT DAVID DANNER, AJV-A421, 405-954-5077. QUALITY 21 CHECKED QUALITY 30 CHECKED					

FIPC BASIC FORM						
PROCEDURE: RNAV (GPS) RWY 23R AMDT 0E			AIRPORT NAME: RICKENBACKER INTL		AIRPORT ID: KLCK	SPECIAL CONTROL NO: BG-02-325-24
FAC ID: KLCK23R		CITY: COLUMBUS			ST: OH	ORIG CHART DATE: 05/16/2024
DFL TYPE: PROC/S	THIRD PARTY: ☐ YES	EST. TIME ON SITE: 0.4	REIMB. NUMBER: AC0721	PTS TASK ID: 8CA4E257BBFA4889809FBE3A521E8D34		
PREFLIGHT NOTES						
REVIEWER: scott wiebe					DATE: 03/28/2024	
COMMENTS:					CHECK ONE:	
					☒ FLT CK REQ ☐ NFCR ☐ REJECT	
					 YES NO	
					CPV COMPLETE?	
					X	
PROCEDURE RESULTS						
INSPECTION DATE: 03/28/2024	CREW #: VN219	N #: N77	INSTRUMENT PROCEDURE STATUS: ☒ SAT ☐ SAT W/CHANGES ☐ UNSAT		ARINC CODING: ☒ SAT ☐ SAT/GOLD ☐ UNSAT	
FLIGHT INSPECTOR SIGNATURE: scott wiebe @ 03/28/2024 14:57			PRINTED NAME: WIEBE, GREGORY SCOTT			NOTAM INITIATED? ☐ YES ☒ NO
FLIGHT INSPECTOR REMARKS:						
IN-FLIGHT OBSTACLE REPORT						
OBSTRUCTION ID #:	COORDINATES OR LOCATION:	GNSS ALTITUDE (MSL):	BAROMETRIC ALTITUDE (MSL):	HEIGHT ABOVE GROUND LEVEL:		

WAAS CH 78421 W23B	APP CRS 232°	Rwy Idg TDZE 743 Apt Elev 744	10913
--	------------------------	---	--------------



RNAV (GPS) RWY 23R
RICKENBACKER INTL (LCK)

RNP APCH - GPS.

⚠ Circling NA northwest of Rwy 5L-23R. For uncompensated Baro-VNAV systems, LNAV/VNAV NA below -16°C or above 54°C. Baro-VNAV NA when using John Glenn Columbus Intl altimeter setting. When local altimeter setting not received, use John Glenn Columbus Intl altimeter setting; increase LPV DA to 978 feet; increase LNAV/VNAV DA to 1041 feet and all visibilities to 1 SM; increase all MDAs 40 feet and Circling Cat D visibility ¼ SM.

MISSED APPROACH:
Climb to 3000 direct COLMU and on track 179° to XUB VOR and hold.

ATIS 132.75	COLUMBUS APP CON 134.0 279.6	RICK TOWER 120.05 348.4	GND CON 125.275 275.8	CLNC DEL 125.275 275.8
-----------------------	--	-----------------------------------	---------------------------------	----------------------------------




3000	COLMU	XUB	VGSI and RNAV glidepath not coincident (VGSI Angle 3.00/TCH 79).	
↑	✧	tr 179°	4 NM	Holding Pattern
1.3 NM to RW23R		HESLA 2400	2400	GP 3.00° TCH 55
2400		2400	2400	2400
1.3		3.7 NM	6.5 NM	
CATEGORY	A	B	C	D
LPV DA	943-¾ 200 (200-¾)			
LNAV/VNAV DA	1006-⅞ 263 (300-⅞)			
LNAV MDA	1220-1	477 (500-1)	1220-1⅓	477 (500-1⅓)
CIRCLING	1240-1	496 (500-1)	1280-1½	1400-2
			536 (600-1½)	656 (700-2)

WAAS CH 78421 W23B	APP CRS 230°	Rwy Idg TDZE 743 Apt Elev 744	10913
--	------------------------	---	--------------


RNAV (GPS) RWY 23R
RICKENBACKER INTL (LCK)

RNP APCH.	MISSED APPROACH: Climb to 3000 direct COLMU and on track 177° to XUB VOR and hold.
⚠ Baro-VNAV NA when using John Glenn Columbus Intl altimeter setting. For uncompensated Baro-VNAV systems, LNAV/VNAV NA below -16°C or above 54°C. Circling NA northwest of Rwy 5L-23R. VDP NA with John Glenn Columbus Intl altimeter setting. When local altimeter setting not received, use John Glenn Columbus Intl altimeter setting: increase LPV DA to 978 feet; increase LNAV/VNAV DA to 1041 feet and all visibilities to 1 SM; increase all MDAs 40 feet and Circling Cat D visibility ¼ SM.	

ATIS 132.75	COLUMBUS APP CON 134.0 279.6	RICK TOWER 120.05 348.4	GND CON 125.275 275.8	CLNC DEL 125.275 275.8
-----------------------	--	-----------------------------------	---------------------------------	----------------------------------



ELEV 744	D	TDZE 743
-----------------	----------	-----------------



EC-2, 07 SEP 2023 to 05 OCT 2023

EC-2, 07 SEP 2023 to 05 OCT 2023

KLCK
RICKENBACKER INTL
COLUMBUS, OH
RNAV (GPS) RWY 23R
ORIG-E
100,000
CIRCLING

Circling CAT A/B ELEVATOR (876)
39-100864

Circling CAT C TOWER (929)
39-103369

Circling CAT D AAO (1100)
Cat D AAO

