



CINCINNATI APP CON 119.7 254.25 D-ATIS 134.375	RNAV 1 - DME/DME/IRU or GPS. RADAR required.
---	---



JAKIE SEVEN ARRIVAL (RNAV) Arrival Routes

COVINGTON, KENTUCKY



JAKIE SEVEN ARRIVAL (RNAV) Arrival Routes

COVINGTON, KENTUCKY

ARRIVAL ROUTE DESCRIPTION

CVG: From JAKIE on track 336° to cross NAVPE at or above 10000, then on track 336° to cross OPAVE between 8000 and 12000.

LANDING CVG RUNWAY 9: From OPAVE on track 334° to cross REENY at or above 8000 and at 210K, then on track 334° to AAJAY, then on track 294° to MAPUC, then on track 276° to cross FLOTT at 6000 and at 210K, then on track 276°. Expect RADAR vectors to final approach course for ILS, GPS, or RNP RWY 9 approach.

LANDING CVG RUNWAY 18L: From OPAVE on track 334° to cross REENY at or above 8000 and at 210K, then on track 334° to AAJAY, then on track 010° to IGOCO, then on track 006° to cross NXHAL at 6000 and at 210K, then on track 006°. Expect RADAR vectors to final approach course for ILS, GPS, or RNP RWY 18L approach.

LANDING CVG RUNWAYS 18C/R: From OPAVE on track 316° to cross FIDEK at or above 8000 and at 210K, then on track 004° to UBEDE, then on track 006° to cross LEWIN at 6000 and at 210K, then on track 006°. Expect RADAR vectors to final approach course for ILS, GPS, or RNP RWY 18C/R approach.

LANDING CVG RUNWAY 27: From OPAVE on track 358° to cross PIVBE at 8000, then on track 358°. Expect RADAR vectors to final approach course for ILS, GPS, or RNP RWY 27 approach.

LANDING CVG RUNWAYS 36L/C/R: From OPAVE on track 276° to cross SPOOD at 8000, then on track 280°. Expect RADAR vectors to final approach course for ILS, GPS, or RNP RWY 36L/C/R approach.

LANDING I69/LUK/HAO: From JAKIE on track 337° to cross TUCKK at 11000, then on track 337°. Expect RADAR vectors to final approach course.

PROTOTYPE-NOT FOR NAVIGATION